



INVITATION TO BID (ITB)

ITB 18-219

GUARDRAIL REPAIR

Invitation to Bid Due: August 7, 2018@ 12noon EST.

Deadline for Questions: August 3, 2018 at 5:00pm

Questions must be directed to:

City of Brookhaven via e-mail: purchasing@brookhavenga.gov

Questions will only be accepted via email to ensure the same information is given to everyone.

A questions addendum will be issued shortly after the deadline and posted on the City's

Purchasing Page.

Instructions to Proposers

All spaced below are to be completed and the Invitation to Bid Letter page must be signed where indicated. Failure to sign and return Invitation to Bid Letter may cause rejection of the Invitation to Bid.

Invitation to Bid of:

Company Name:

Contact Name: _____

Address: _____

Telephone: _____ Facsimile: _____

Email: _____

Submit Invitation to Bid (ITB) to:
City of Brookhaven Purchasing Office

Invitation to Bid (ITB) shall be presented in a sealed opaque envelope with the bid number and name ITB 18-219 GUARDRAIL REPAIR clearly marked on the outside of the envelope. The name of the company or firm submitting a bid should also be clearly marked on the outside of the envelope. ONE (1) ORIGINAL PAPER COPY AND ONE DISK/FLASH DRIVE OF THE BID MUST BE SUBMITTED.

All documents must be submitted with bid.

Guardrail repair scope

Location: 1204 Lake Hearn Drive, northwest corner of Perimeter Center Parkway and Lake Hearn Drive.



Total guardrail length: 149 ft, w-beam transitions into bridge rail of Perimeter Center Parkway Bridge.

Section to Section damage: 63 ft at the midpoint of a convex curve

Effective guardrail damaged: 50 ft and yielded steel posts

Installation needs:

Remove and replace Seven (7) six-foot steel posts (4" x 5 7/8")

Mounting height- top edge of 13" galvanized guardrail to be 29-inches from finish grade.

Replace Eight (8) 14.5-inch rubber spacer blocks for steel posts with hardware to attach W-Beam.

Two white in-channel reflector tabs

City has slightly used longitudinal guardrail system similar to one damaged at our maintenance yard on Osborne Road to fulfill all hardware needs. Maintenance yard is four (4) miles from repair site. See photos. Brookhaven services requested is to remove damaged W-Beam and uproot posts and drive new posts and set replacement W-Beam.

The City does not have any 12'6" convex radius guardrail sections available for use. These are to be furnished by the contractor as needed to maintain the setback distance from the face of curb and sidewalk and price to furnish included in the estimate.

Contractor must provide their availability to start as we have the materials to repair this single location in our maintenance yard.

Contractor is required to have insurance once contracted has been awarded.

Total Flat Fee Cost \$ _____

Your estimated Start time _____

All documents must be submitted with bid.

Photos of repair site and city furnished hardware





City furnished reflectors to be installed in replaced section.



City furnished steel posts, w-beams, and spacer blocks to be installed in replaced section.



City furnished steel posts, w-beams, and spacer blocks to be installed in replaced section.



City furnished steel posts, w-beams, and spacer blocks to be installed in replaced section.

All documents must be submitted with bid.