

**DWM Incomplete Work Areas
in
Brookhaven Rights-of-Way**

173 Total Locations Requiring DWM Repairs (DWM Work Orders)				98 Known DWM Work Orders Completed, 8/20-Present			16 Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	AREA AND TYPE	Road Plate Used	COMMENTS	
2059434		8/7/2020	1420 1430 1445 1462 Brawley Circle	1430 1445 1462 Brawley Circle	Two depressions in the road 3-inches deep formed last year and no repairs have been made. First Reported on 8/7/2020.		Inspected 9/12/2022 there has been no repairs done to the sinkhole. Grass is growing out of the sinkhole.	
2063959		8/19/2020	4180 4352 4368 Berkford Circle	4352 4368 Berkford Circle	A depression in the road 3-inches deep formed last year and no repairs have been made. First reported on 8/29/2020.		Inspected 9/12/2022 there has been no repairs done.	
21048724 22023281		5/24/2021 3/14/2022	1855 Tobey Rd NE	Tobey Rd NE	A sinkhole formed 6-ft deep, 6-ft in length, and, 4 -feet wide underneath the road in line with the sanitary sewer line from this property to the middle of the road. The sinkhole was repaired with WO 21048724. It was noted on 3/11/2022 that it had reopened and no concrete cap was installed on the trench.		Inspected 9/12/2022 there is GAB covering the hole. There is no road plate covering the GAB and it is washing out of the hole.	
21062135		7/12/2021 1/18/2022	2622 Briarcliff Rd NE	Briarcliff Rd NE	Pothole has opened up once more due to contact water spewing from it. First reported on 7/12/21. The City of Brookhaven Street crew repaired only the pothole due to the delay by DWM responding to our SR. A second SR has been submitted on 10/6/21. DWM has excavated the pothole and installed a road plate.	X	The water leak has been repaired and a poorly installed asphalt patch is in its place. Two other trenches have been made across the street. One has GAB and the other is covered with a road plate.	
21063205		7/15/2021	1897 E Roxboro Rd NE	E Roxboro Rd NE	Work on fire hydrant. Tree on the sidewalk and sinkhole at edge of it. DWM cones installed. There is a small sinkhole next to the fire hydrant.		Inspected 9/19/2022, they poured a concrete patch that is lower than the existing sidewalk. They need to remove the whole panel and	
21069929		8/3/2021	1514 Ragley Hall Rd NE	Ragley Hall Rd NE	A depression formed underneath the sidewalk. The sidewalk collapsed 3-inches above the sanitary and water service lines to this property.		Inspected 9/19/2022 the sidewalk has been repaired, however the landscaping still needs to be done.	
21071905		8/9/2021	2132 Havenwood Trail NE	Havenwood Trail NE	The water meter on the sidewalk has sunk and created a dangerous trip hazard.		Inspected 9/15/2022, the water meter is still down.	
21085424		9/14/2021	4560 E Brookhaven Dr	E Brookhaven Dr	Large depression has formed in the middle of the road near the sanitary sewer line.			
21091053		9/28/2021	2332 Drew Valley Rd	Drew Valley Rd	There is a large depression over the sanitary sewer service line in the middle of the road.		Inspected 9/12/2022 the repairs have not been done.	
21091564 22001249		10/1/2021 01/13/2022	2484 Oostanaula Dr. NE	Oostanaula Dr. NE	Three road plates installed over a trench for a water main break repaired on 7/22. 3 road plates have been installed and there is a water leak near the fire hydrant spewing water to the road.		Inspected on 10/24 and the concrete curb has been repaired. Left is the restoration of the shoulder.	
21094283		10/12/2021	3882 Ashford Dunwoody Rd	Ashford Dunwoody Rd	DWM made repairs to a water main break and damaged the sidewalk at both ends and behind of it. The water break caused the sidewalk to sink before the catch basin creating a trip hazard. DWM has to demo and repair the sidewalk. The repairs were made the first week of October.			
21012958			2002 Drew Valley Rd	Drew Valley Rd	There is a large depression over the sanitary sewer service line to this property.		Work Order 22004115 was made to prepare the street for asphalt	

**DWM Incomplete Work Areas
in
Brookhaven Rights-of-Way**

173 Total Locations Requiring DWM Repairs (DWM Work Orders)			98 Known DWM Work Orders Completed, 8/20-Present			16 Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	AREA AND TYPE	Road Plate Used	COMMENTS
21023844		12/15/2021	3246 Lynwood Dr	Lynwood Dr	A depression has formed over the sanitary sewer line. It is approximately 3-inches deep and it is happening on an old road repairs. It seems to be the SS service line to this property.		
22001232		1/11/2022	2638 Drew Valley Rd	Drew Valley Rd	Repairs to a water valve and water main were made and it damaged the ADA ramp. The water valve was left above the surface of the road.		Inspected 9/12/2020 the water valve is still leaking and the ADA ramp needs to be removed and replaced.
22009036		1/28/2022	1865 Canmont Dr	Canmont Dr	A previously repaired patch near and around the DWM sanitary sewer manhole has dropped approximately 3-inches.		Inspected 9/15/2022, no work has been done.
22011262		2/1/2022	1451 Sylvan Circle	Sylvan Circle	A depression has formed in the middle of the road along with the sanitary sewer mainline. The depression is approximately 6-ft long by 3-ft wide and 3-inches deep.		Inspected 9/12/2022 the repair has not been done.
21015773		2/18/2022	1543 Aragon Way	Aragon Way	A 5-ft deep sinkhole has formed between the granite curb and the water meter. The mailbox has fallen into the sinkhole.		Inspected 9/16/2022, there has been no work done.
22015961		2/18/2022	1537 Aragon Way	Aragon Way	In the middle of the road above the Sanitary Sewer line and at the edge of a trench the road is sinking.		Inspected 9/16/2022, there has been no work done.
		2/18/2022	3012 Surrey Ln	Surrey Ln	The road is sinking from the middle of the road towards the water meter.		Inspected 9/15/2022, asphalt has been placed in the depression, however the street is still sinking in that area.
22016627 – COB		2/22/2022	2925 Skyland Dr	Skyland Dr	A sinkhole has developed at the edge of the road with the granite curb in line with the water service line to this property. DWM has stated the sinkhole not related to the water main underneath of it.		Inspected 9/15/2022, PW called Atl. Gas& light to check for possible gas leak, nothing found. Will notify the owner of what was found.
		2/28/2022	2367 Ewing Dr	Ewing Dr	A sinkhole has formed underneath the concrete cap installed by DWM.		Inspected 9/12/2022 the repair has not been done.
22018437		2/28/2022	2373 Ewing Dr	Ewing Dr	A sinkhole has formed underneath the concrete cap installed by DWM.		Inspected 9/12/2022 the repair has not been done.
21056189		2/28/2022	4189 Shawnee Ln	Shawnee Ln	Three sections of the granite curbs were removed or damaged during repairs to the water main. Runoff from the street has caused shoulder erosion.		
		3/31/2022	1552 Brawley Circle	Brawley Circle	A 3-inch depression has formed in the road above the sanitary sewer main.		Inspected 9/12/2022, work not done on depression in street.

**DWM Incomplete Work Areas
in
Brookhaven Rights-of-Way**

173 Total Locations Requiring DWM Repairs (DWM Work Orders)			98 Known DWM Work Orders Completed, 8/20-Present			16 Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	AREA AND TYPE	Road Plate Used	COMMENTS
22036023		4/26/2022	4166 Candler Lake W	Candler Lake W	3 depressions have formed above the SS main which have caused the entire road to further break.		Inspected 9/16/2022, there has been no work done.
22036023		4/26/2022	4128 Candler Lake W	Candler Lake W	A large depression has formed in the middle of the road above the SS mainline. The depression is in line with the SS service line to this property.		Inspected 9/16/2022, there has been no work done.
22036028		4/26/2022	4046 Candler Lake W	Candler Lake W	A large depression has formed from the curb to the middle of the road. A locate811 has been requested as this depression may be water or sewer.		Inspected 9/16/2022, there has been no work done.
22036495		4/28/2022	3847 Granger Dr	Granger Dr	The concrete collar of manhole # 18-325-s130 is broken and is causing the road to break around it.		The repairs to the catch basin is being done by Corbett.
22037156		5/2/2022	1310 Ragley Hall Rd	Ragley Hall Rd	Two depressions in the road have been observed. One is across a water leak and above the SS and the other is above the SS main near manhole # 18-302-s066.		Inspected 9/19/2022 not repaired.
22046688		5/27/2022	3707 Lambert Ln	Lambert Ln	A sinkhole has developed underneath the concrete gutter and spreads towards the middle of the road in line with the SS service line to the SS main. It is approx. 4-ft deep.		Inspected 9/20/2022, no repairs have been made.
22052846		6/17/2022	2794 Ashford Rd	Ashford Rd	A sinkhole has developed next to repairs made by DWM to another sinkhole at 2791 Ashford Rd.		Inspected 9/16/2022, there has been no work done. The sinkhole has started to spread, the pavement is being undermined.
22057005		7/1/2022	4040 Peachtree Rd NE	Peachtree Rd NE		X	Inspected 9/16/2022 not repaired. There is a steel plate over the hole.
22060218		7/8/2022 9/1/2022	3308 Finistere Ct	Finistere Ct	A 3x3 and 8 inches deep sinkhole has formed over the water service line to this property. The City installed cones and a barrel with caution and a request was made to DWM to install a road plate.		The initial water service line was repaired, GAB added but no road plate over the trench. Now another water leak has developed underneath the concrete curb before the water meter and is all over the road.

**DWM Incomplete Work Areas
in
Brookhaven Rights-of-Way**

173 Total Locations Requiring DWM Repairs (DWM Work Orders)				98 Known DWM Work Orders Completed, 8/20-Present			16 Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	AREA AND TYPE	Road Plate Used	COMMENTS	
22059814		7/12/2022	1448 1457 1466 Grant Dr.	1457 1466 Grant Dr.	A large depression has formed in the road above the sanitary sewer main and where the service line to this property is located.		Inspected 12/1/2022 the repairs DWM was done and they placed GAB to fill in the hole, the GAB has eroded and noe there has developed a hole in the road that is more than a foot deep insome areas. It has been reported to DWM.	
22057294		8/15/2022	4170 Ashford Dunwoody Rd	Ashford Dunwoody Rd	More than 20-FT of the sidewalk and a portion of the road were removed for a water leak. Your crews left a mess with asphalt pile up in the beauty strip, concrete on top of the sidewalk, a dead tree on the sidewalk, a depression, and failed to level with GAB where the sidewalk used to be so it could be used by residents of the area. GAB is on the road and at the entrance to the apartments plus on the ADA ramp.		Inspected 9/19/2022 the sidewalk has been pour back, the brick pavers still need to be put back down and the landscaping needs to be done.	
22073233 22100092		8/16/2022 11/22/2022	2572 Apple Valley Rd	Apple Valley Rd	A 4-FT deep sinkhole has formed at the edge of the concrete sidewalk near the sanitary sewer service line and between the cleanup and the manhole in the middle of the street.	X	Inspected 11/22/2022 the road repair has not been done and the fill has washed out and now there is a 6" hole in parts of the trench.	
22071998		8/19/2022	4279 Ashwoody Trl NE	Ashwoody Trl NE	There is a large amount of water flow from the water meter at this property flowing into the road and the stormwater is equivalent to 5 gallons per minute.		Inspected 9/19/2022, the sidewalk has been poured back. Thetopsoi; and soil needs to be put down.	
22075222		8/23/2022	2791 Ashford Rd	Ashford Rd	Under the previous repairs for DWM WO 21079815, the sewer laterals for 2791 and 2794 were repaired but the COB or Dekalb Trench Standards were not followed. A benched concrete cap was not installed and the road was not milled and paved from BOC to BOC. The road has begun to sink between these two repairs.		Inspected 9/16/2022, the sinkhole has spread under the pavement.	
		8/24/2022	1697 Wawona Terrace	Wawona Terrace	Emergency repairs for a water main break. The repairs to the road and landscaping are scheduled to be completed by 8/26/22		Inspected 9/19/2022, the landscaping still needs to be completed.	
21116773			1509 Tryon Rd	Tryon Rd	A break in the water main prompted DWM to remove 4 sections of the sidewalk and the landscaping on both sides of it. The sidewalk has been replaced but not the landscape on both sides of the sidewalk, and the granite curbs not raised.		Insspected 9/15/2022 the sidealk has been replaced. The landscaping has not been done, this locatoin is by the elementary school.	
		9/1/2022	1285 Old Johnson Ferry Rd	Old Johnson Ferry Rd	The ADA ramp has been removed for repairs to the water main. GAB was installed but not safety cones or caution tape. The GAB has a washout at the edge with the pavement creating dangerous conditions for pedestrians.		A valve was installed in the ADA ramp area and a ramp was poured back around the water valve. This does not comply with ADA codes, the valve has to be relocated. 11/14/2022	

**DWM Incomplete Work Areas
in
Brookhaven Rights-of-Way**

173 Total Locations Requiring DWM Repairs (DWM Work Orders)			98 Known DWM Work Orders Completed, 8/20-Present			16 Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	AREA AND TYPE	Road Plate Used	COMMENTS
21087723		9/8/2022	2896 Caldwell Rd	Caldwell Rd	10-FT of the sidewalk was removed for repairs to the water main. GAB and no safety cones, barrels, or caution tape were installed.		The sidewalk has been repaired. Forms have not been removed and landscape restoration has yet to be completed.
22072287		9/8/2022	1342 Old Johnson Ferry Rd	Old Johnson Ferry Rd	5 sections of the sidewalk have been removed for repairs to the water main. No cones or caution tape was used.		
22082319		9/14/2022	2933 Parkridge Dr	Parkridge Dr	A minor water leak around the water meter has caused the granite curbs to collapse. Due to the slope of the front yard, the water is traveling underneath the granite curbs. We have replaced some granite curbs and will wait for DWM to investigate the leak before completing our repairs.		
		9/15/2022	1314 Beech Haven	Beech Haven	A water service line has hit and is leaking at the entrance to the park. DWM came out and dug up two locations but did not repair the leak. They covered the holes with GAB. Water is running into the street.		Inspected 9/15/2022, no repairs have been done.
22088465		9/15/2022	3190 Caldwell Rd.	Caldwell Rd.	DWM did an emergency repair on the sanitary lateral, they backfilled with GAB. There is no plate over the hole.		Checked on 11/15/2022 DWM has placed a steel plate over the hole.
		9/15/2022	1348 N Cliff Valley Way		The lid for the water meter # 18-198-12064 has broken creating a dangerous trip hazard.		
		9/21/2022	3217 Mae Ave	Mae Ave	A water leak has been reported via an SK in the middle of the road. We have reported it to DWM and it is being scheduled to be repaired on		
		9/22/2022	2297 Nesbitt Dr	Nesbitt Dr	A trench in the middle of the road has been made and an excess amount of GAB added to it. The GAB has created a hump in the street. Additionally,		
		9/22/2022	1518 Grant Dr	Grant Dr	A depression has developed on a patch previously repaired by the City. This patch was completed because DWM had not accepted responsibility for the trench in the road.		
		9/20/2022	1970 Roxboro Rd.	Roxboro Rd.	Repairs were made to a DWM pipe, they placed a steel plate over the hole.		
		9/20/2022	1897 Roxboro Rd.	Roxboro Rd.	In the intersection there is a water valve lid missing.		

**DWM Incomplete Work Areas
in
Brookhaven Rights-of-Way**

173 Total Locations Requiring DWM Repairs (DWM Work Orders)			98 Known DWM Work Orders Completed, 8/20-Present			16 Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	AREA AND TYPE	Road Plate Used	COMMENTS
		9/20/2022	1314 Beech Haven Dr.	Beech Haven Dr.	A water service line was hit by the entrance of the park. DWM came out and dug up two locations but did not repair the leak. The holes are covered with GAB with no road plates.		
22088462		9/15/2022	2673 N. Thompson Rd.	N. Thompson Rd.	There is sinkhole forming in the middle of the street above the sanitary line.		
		9/15/2022	2827 N. Thompson Rd.	N. Thompson Rd.	There is a depression in the road that needs to be investigated for a possible sanitary failure.		
22084419		9/23/2022	4082 Nancy Creek Way	Nancy Creek Way	Emergency repairs to the water service line to this property were made on 9/22/22. Mud and sediments were left on the road and in the stormwater conveyance system.		
		10/3/2022	2335 Briarwood Way	Briarwood Way	The entrance to the park was cut and open above the 20-inch water main. The trench was not squared and no road plates install. GAB was installed and left debris all over the road.		
		10/4/2022	2430 Coosawattee Dr	Coosawattee Dr	A sinkhole has developed in the beauty strip. The nearest utility is the sanitary sewer and we have reported it to DWM for further inspection		
		10/4/2022	1583 Fearn Circle	Fearn Circle	Repairs to a water service lateral to this property were completed but not all the sod was installed.		
		10/4/2022	2420 Drew Valley Rd	Drew Valley Rd	The shoulder of the road, granite curbs, and pavement were disturbed for repairs to the water main and the service line to this property. Mulch was installed but no other repairs made.		
22089511		10/12/2022	2765 Osborne Rd	Osborne Rd	A water leak underneath the driveway to this property was reported to DWM.		

**DWM Incomplete Work Areas
in
Brookhaven Rights-of-Way**

173 Total Locations Requiring DWM Repairs (DWM Work Orders)			98 Known DWM Work Orders Completed, 8/20-Present			16 Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	AREA AND TYPE	Road Plate Used	COMMENTS
22083979		10/13/2022	1414 Ragley Hall Dr	Ragley Hall Dr	3 sections of the sidewalk were removed for repairs to the water main. GAB was added, and seed and straw to the shoulder and beauty strip.		
		10/13/2022	3505 Hampton Hall Way	Hampton Hall Way	DWM repair the water main on the shoulder of the road. The shoulder has not been restored.		
		10/24/2020	1247 Oostanula Dr	Oostanula Dr	The driveway and part of the road were removed for repairs to the water main and lateral to this home. GAB was added to the driveway and mud was not removed from the road.		
		10/31/2022	1855, 1861 Dresden Dr	1861 Dresden Dr	Residents reported DWM completed sanitary sewer work but the shoulder is sinking.		
22097416		11/14/2022	1242 Goodwin Rd	Goodwin Rd	A depression in the road has developed. The depression has developed above the sanitary sewer lateral.		
		11/11/2022	1834 Buckhead Ln	Buckhead Ln	A pothole was made on the beauty strip of the shoulder of the road Dekalb Watershed and not closed.		
22072849		11/14/2022	2968 Cravenridge Dr.	Cravenridge Dr.	The crosswalk to the Ashford Park Elementary School was removed and damaged by DWM during maintenance to the water main. The sidewalk at the end of the crosswalk was partially repaired with asphalt including the trip hazards.		
		11/15/2022	1302 W. Nancy Creek Rd	W. Nancy Creek Rd	DWM was called out for an emergency water leak at the service meter for this house. They repaired the line was exposed part of the driveway and washed away part of the front yard.		
22092708 22092740 22093845		10/15/2022	1582 Trentwood Pl	Trentwood Pl	Water main repairs in front of this property were made by DWM. Left to repair is the landscaping, granite curbs and the road.		
22097532		11/21/2022	2455 Ellijay Dr.	Ellijay Dr.	DMW perform a point repair that had been reported by the homeowner.		

**DWM Incomplete Work Areas
in
Brookhaven Rights-of-Way**

173 Total Locations Requiring DWM Repairs (DWM Work Orders)			98 Known DWM Work Orders Completed, 8/20-Present			16 Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	AREA AND TYPE	Road Plate Used	COMMENTS
		12/21/2022	1300 Hermance Dr	Hermance Dr	Repairs to the water main were conducted by DWM. The northbound lane was removed and GAB was added to the trench. Rain events have continuously washed away		
		1/6/2023	3528 Telfair Way	Telfair Way	The concrete curb and gutter and one lane of the road have been removed for repairs to the water main. GAB was added to the trench.		
		1/6/2022	3197 Lynwood Dr	Lynwood Dr	A 14-FT by 8-FT trench was made for repairs to the water main and GAB was added to the trench. Recent rain events have washed away the GAB which has been promptly repaired by DWM.		
		1/6/2023	3215 Lynwood Dr	Lynwood Dr	A 3-FT by 3-FT trench has been made for repairs to the water main. The trench was filled with GAB.		