223 Total Loo	ations Requiri	ng DWM Repairs	(DWM Work Orders)	195 Known DWM Work	Orders Completed, 8/20-Present	28 Locations w	ith Road Plates Covering Needed Repair
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
21085424		9/14/2021 4/3/2023	4560 E Brookhaven Dr	E Brookhaven Dr	Large depression has formed in the middle of the road near the sanitary sewer line.		Two other depressions over the sanitary sewer main and laterals have formed. Inspected on 7/13/2023
21091564 22001249 23012287		10/1/2021 01/13/2022	2484 Oostanaula Dr. NE	Oostanaula Dr. NE	The road has been poorly repaired with no concrete cap. The entire asphalt patch is sinking.		Inspected on 11/2/2023
22011262		2/1/2022	1451 Sylvan Circle	Sylvan Circle	A depression has formed in the middle of the road along with the sanitary sewer mainline. The depression is approximately 6-ft long by 3-ft wide and 3-inches deep.		Inspected 11/7/2023 the repair has not been completed.
22015961		2/18/2022	1537 Aragon Way	Aragon Way	In the middle of the road above the Sanitary Sewer line and at the edge of a trench the road is sinking.		Inspected on 11/2/2023
22057005		7/1/2022 6/27/2023	4040 Peachtree Rd NE	Peachtree Rd NE	The repair was done on East Brookhaven Rd. in front of Dunkin Donuts. New problems were reported and a road plate was installed over 9 months ago	x	To be repaired by A&S Paving. No schedule has been provided.
		9/1/2022	1285 Old Johnson Ferry Rd	Old Johnson Ferry Rd	The ADA ramp has been removed for repairs to the water main. GAB was installed but not safety cones or caution tape. The GAB has a washout at the edge with the pavement creating dangerous conditions for pedestrians.		A valve was installed in the ADA ramp area and a ramp was poured back around the water valve. This does not comply with ADA codes, the valve has to be relocated. 11/14/2022
23012449		2/13/2023	2827 N. Thompson Rd.	N. Thompson Rd.	There is a deep depression forming to the right of the driveway. A previous DWM sanitary sewer repair is sinking in front of the driveway.		Inspected on 11/1/2023. DWM will be repairing the street depressions. It has been placed on hold.
22097416		11/14/2022	1242 Goodwin Rd	Goodwin Rd	A depression in the road has developed. The depression has developed above the sanitary sewer lateral.	x	Inspected on 11/2/2023
22092740 22093845		11/18/2022	1536 Trentwood Pl	Trentwood Pl	Water main repairs in front of this property were made by DWM. Left to repair is the landscaping, granite curbs and the road.		Updated on 11/2/2023

223 Total Loo	cations Requirir	ng DWM Repairs	(DWM Work Orders)	195 Known DWM Work	Orders Completed, 8/20-Present	28 Locations w	Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES	
		1/23/2023	3517 Ashford Dunwoody RD NE	Ashford Dunwoody RD NE	There are various potholes made to uncover water valves near the park. These have not been raised creating dangerous conditions for drivers and cyclists.			
23020321		3/2/2023	2573 Skyland Trail	Skyland Trail	3 large sinkholes and a small one have formed above and in front of the water main alongside the frontage of this property.			
23028044		4/3/2023	1190 Pine Grove Ave	Pine Grove Ave	A large depression on the asphalt has formed from the edge of the paving to the sanitary sewer manhole.		Insspected on 7/13/2023. No repairs have been completed.	
23020683		4/6/2023	3320 Woodrow Way	Woodrow Way	Cuts to the road and shoulder were made for repairs to the sanitary sewer lateral to this property. The trench was repaired with GAB and no road plates have been installed		The paving has been completed. The remaining repairs are for the concrete C&G.	
23029788		4/6/2023	3273 Stratfield Dr	Stratfield Dr	A long depression has from 3280 to 3273 above the sanitary sewer main and between two manholes and Lift Station #50		Inspected on 7/13/2023. No repairs have been completed.	
24040494		5/16/2023	4006 E Brookhaven Dr	E Brookhaven Dr	A four-foot by two-foot wide sinkhole has formed in front of this property DW. A safety cone has been installed over the sinkhole.		Inspected on 12/8/2023. No repairs have been completed.	
23404374		6/6/2023	1271 Star Dr	Star Dr	A 6 feet long by 4 feet wide sinkhole has formed on the street above this property's sanitary sewer service line. DWM has repair the sinkhole and added GAB to the trench.		Inspected on 12/8/2023	
23052473		7/11/2023	2864 Duncan Dr	Duncan Dr	The sinkhole was repaired by DWM and the street pavement. Left to be completed is the shoulder restoration.		Inspected 11/10/2023	
23059186		8/8/2023	1217 Kendrick Rd	Kendrick Rd	During the recent storm events, a large depression/sinkhole has formed above the sanitary sewer main. It is 6 feet long by 3 feet wide and continues to grow. A few feet from the depression, a crack in the street from curb to curb has formed. It continues to the shoulder at 1220 Kendrick Rd where another sinkhole is forming.	x		

223 Total Lo	cations Requiri	ng DWM Repairs	(DWM Work Orders)	195 Known DWM Work	Orders Completed, 8/20-Present	28 Locations w	ith Road Plates Covering Needed Repair
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
		11/2/2023	1050 Capital Club Circle	Capital Club Circle	On the week prior to October 23rd, DWM responded to a water leak request submitted by Hyper Networks at this location. The front yard of this property was severely damaged and not properly restored.		
		9/18/2023	1770 Duke Rd	Duke Rd	Repairs to the water main underneath the driveway to this property were completed last week. GAB was installed on the driveway. The street was severely compromised during the water break and repairs. At least half of the street must be milled and paved.		
23073739 23073740		11/2/2023	1158 W Nancy Creek Dr	W Nancy Creek Dr	A water leak underneath the driveway of this property was repaired. A new driveway and two sections of the sidewalk were installed. However, the new driveway slope is 4 and 5% which does not meet ADA requirements.		
		11/7/2023	2753/2748 S Bamby Ln	S Bamby Ln	A water service work was completed at this location and a road plate was installed across the street at 2748 S Bamby Ln. The receipt number for this work is 23069884.	x	
23084017		11/7/2023	3188 Inman Dr	Inman Dr	The road is caving in above the sanitary sewer main.		
23027989		4/3/2023	3292 Buford HWY	Buford HWY	On the N Cliff Valley Way side of the AMR building. The shoulder has yet to be repaired by DWM.		Inspected on 11/7/2023.
21105504 23062530		11/2/2023	1082 Mendell Circle	Mendell Circle	A sinkhole has developed next to a previous DWM street repair.		
23094219		12/18/2023	1093 W Nancy Creek Dr	W Nancy Creek Dr	A sinkhole has formed near the center of the street and the SS main. PW investigated and found a sinkhole underneath the street. A temporary patch was installed and DWM notified.		
		12/15/2023	1850 Tobey Rd	Tobey Rd	A sinkhole has formed in the middle of the street above the SS main.	x	
2059434 2059640 23082146		8/7/2020 10/30/2023	1462 Brawley Circle	Brawley Circle	A depression above the sanitary sewer main developed early last year. This was previously reported, however, no work has ever been observed to repair the pavement. Please send a crew to investigate and make the necessary repairs. Remember that poor compaction at the time the sanitary sewer was installed causes the pavement to sink and DWM is		Reported once more on 10/30/23

223 Total Loo	cations Requirir	ng DWM Repairs	(DWM Work Orders)	195 Known DWM Work	Orders Completed, 8/20-Present	28 Locations w	vith Road Plates Covering Needed Repair
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
PW	12/8/2023	9/15/2022	1348 N Cliff Valley Way		The lid has been replaced by DWM. The PW Dept will complete the sidewalk repairs.		Inspected on 12/8/2023
23077643	12/5/2023	11/7/2023	2842 Parkridge Dr	Parkridge Dr	SS service line repairs were recently made and GAB was added to the trench.		The street has been repaired by A&S Paving.
	11/16/2023	9/8/2023	1889 Curtis Dr	Curtis Dr	A water main leak occurred near a gate valve. Repairs were completed by DWM however the trench and the shoulder have not been repaired. The site was not secured with caution tape.		Repaired by DWM Water Meter Division.
23011860	7/26/2023	6/14/2022 2/10/2023	2002 Drew Valley Rd	Drew Valley Rd	There is a large depression over the sanitary sewer service line to this property.		Repaired by OPTECH with WO 9036
21023844 23037773	11/17/2023	12/15/2021 8/7/2023	3243 Lynwood Dr	Lynwood Dr	A depression has formed over the sanitary sewer line. It is approximately 3 inches deep and it is happening on old road repairs. It seems to be the SS service line to this property. Repairs have been completed and GAB added to the trench.		The street has been repaired by A&S Paving.
22009036	11/8/2023	1/28/2022	1865 Canmont Dr	Canmont Dr	A previously repaired patch near and around the DWM sanitary sewer manhole has dropped approximately 3-inches.		Inspected on 11/7/2023. No changes to the pavement around the manhole concrete ring. This will be closed at this time.
	11/2/2023	2/18/2022	3012 Surrey Ln	Surrey Ln	The road is sinking from the middle of the road towards the water meter.		Repaired by A&S Paving

223 Total Loc	ations Requirir	ng DWM Repairs	(DWM Work Orders)	195 Known DWM Work	Orders Completed, 8/20-Present	28 Locations w	vith Road Plates Covering Needed Repair
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
22072287	11/3/2023	9/8/2022	1342 Old Johnson Ferry Rd	Old Johnson Ferry Rd	5 sections of the sidewalk have been removed for repairs to the water main. No cones or caution tape was used.		Has been repaired.
	11/7/2023	9/21/2022	3217 Mae Ave	Mae Ave	A water leak has been reported via an SR in the middle of the road. We have reported it to DWM. A cold patch was installed with no concrete cap.		The street has been repaired.
	11/2/2023	9/20/2022	1257 Goodwin Rd	Goodwin Rd	In the intersection of Goodwin and Roxboro, there is a water valve lid missing.		Optech will repair this.
22108893	11/17/2023	1/6/2022	3197 Lynwood Dr	Lynwood Dr	A 14-FT by 8-FT trench was made for repairs to the water main and GAB was added to the trench. Recent rain events have washed away the GAB which has been promptly repaired by DWM.		The Street has been repaired. 11/17/2023
22108893	11/17/2023	1/6/2023	3215 Lynwood Dr	Lynwood Dr	A 3-FT by 3-FT trench has been made for repairs to the water main. The trench was filled with GAB.		The Street has been repaired. 11/17/2023
23021770	11/8/2023	3/9/2023	57 Executive Park South	Executive Park South	A trench made for the water service connection to the new apartment complex on 50 Executive Park South is sinking and the pavement next to it is as well.		The street has been repaired.
23027989	10/26/2023	4/3/2023	1470 N Cliff Valley Way	N Cliff Valley Way	Water is bubbling next to the sidewalk. The water is flowing to a water vault owned by AT&T. AT&T has been notified of a sinkhole forming near their cabinets.		The water leak originated in the AMR parking lot. This has been repaired.
23029792	11/2/2023	4/6/2023	2533 Skyland Trl	Skyland Trl	A sinkhole has developed at the edge of the road with the granite curb above the water service line to this property. A safety cone was placed over the depression on the road.		To be repaired by OPTECH

223 Total Lo	cations Requiri	ng DWM Repairs	s (DWM Work Orders)	195 Known DWM Work	Orders Completed, 8/20-Present	28 Locations with Road Plates Covering Needed Repair		
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES	
	11/3/2023	5/4/2023	3653 Brookleigh Ln	Brookleigh Ln	A large sinkhole is forming on the beauty strip at the entrance of Brookleigh Ln on Ashton Woods. The sinkhole is above the mater main.		To be repaired by OPTECH	
23048398	11/7/2023	6/20/2023	2577 Ashford Rd	Ashford Rd	Repairs to the water service lateral to this property have been completed once before on the shoulder of the street. Now a large depression has formed in the street in line with the previous repairs. The depression is 4 feet wide by 6 feet long and 4 inches deep. Please, treat this as an emergency and send a crew asap.		the street has been repaired.	
	11/7/2023	6/20/2023	3262 Woodrow Way	Woodrow Way	A depression has been forming at the intersection of Breton Circle and Woodrow Way. The City of Brookhaven has twice in the past, added pavement level with the street, and has continued to drop. Depression is occurring near the sanitary sewer main.		The pavement was repaired by OPTECH	
	10/31/2023	6/21/2023	3968 Ashford Dunwoody Rd	Ashford Dunwoody Rd	Scheduled work for the installation of a new water service line which resulted in an open cut in the middle of the street, and the removal of a section of sidewalk. A road plate has been installed.	x	The sidewalk and pavement have been repaired	
23061312	11/7/2023	8/16/2023	1701 Dresden Dr	Dresden Dr	There is a sinkhole developing behind the granite curb and inline with the water service lateral to this property. The sinkhole continues underneath the roadway towards the center of the street. Please, send a crew to investigate whether this is related to the water or sanitary sewer laterals.		To be Repaired by Optech	
	10/30/2023	8/22/2023	3206 Osborne Rd	Osborne Rd	A depression above the water main has been observed. There are 3 valve covers that have sunk with the street and need to be raised once the street is repaired		Repaired by Optech with WO 9172	
23063796	10/31/2023	8/25/2023	1000 Byrnwyck Rd	Byrnwyck Rd	A water leak has developed behind and underneath the concrete C&G.		The street has been repaired.	
	10/31/2023	8/30/2023	3856 Parkcrest Dr	Parkcrest Dr	Recently, DWM completed repairs on a water service line at this address. The trench was filled with GAB instead of placing a road plate as it is required by Dekalb County and the City of Brookhaven Trench standards. This section of Parkcrest is on a steep slope and recent rain events have created a 4-foot deep by 6-foot long sinkhole at the edge of the pavement. Please treat this as an emergency and send a crew to install a road plate		Te pavement has been repaired.	

223 Total Loo	cations Requirin	ng DWM Repairs	(DWM Work Orders)	195 Known DWM Work	Orders Completed, 8/20-Present	28 Locations w	vith Road Plates Covering Needed Repair
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
	11/7/2023	5/16/2023	2889 Parkridge Dr	Parkridge Dr	Water main repair on half the intersection with Tobey Rd.		Pavement completed on 11/7/2023
23071560	11/17/2023	9/18/2023	1508 Cortez Ln	Cortez Ln	A sinkhole has formed above the sanitary sewer main. The sinkhole was related to a water main leak. DWM Water Div. has responded however the entire intersection was removed including the granite curbs. Pending schedule for the repairs of the shoulder, landscaping, granite curbs, and the street.		The intersection has been repaired by A&S Paving.
21087723	8/9/2023	9/8/2022	2896 Caldwell Rd	Caldwell Rd	10-FT of the sidewalk was removed for repairs to the water main. GAB and no safety cones, barrels, or caution tape were installed.		The sidewalk has been repaired. Forms have not been removed and landscape restoration has yet to be completed. The surface of the new SW is substandard.
22088462	7/19/2023	9/15/2022	2673 N. Thompson Rd.	N. Thompson Rd.	There is a sinkhole forming in the middle of the street above the sanitary line.		DWM CCTV their line and found no issues. Insist it is for the COB to repair. Repaired by the PW Dept.
	7/19/2023	11/15/2022	1302 W. Nancy Creek Rd	W. Nancy Creek Rd	DWM was called out for an emergency water leak at the service meter for this house. They repaired the line that was exposed to part of the driveway and washed away part of the front yard.		It has been repaired.
23005011 23005284	4/11/2023	1/6/2023 2/10/2023	3528 Telfair Way	Telfair Way	The concrete curb and gutter and one lane of the road have been removed for repairs to the water main. GAB was added to the trench.		Repaired on 4/11/23
	7/20/2023	1/24/2023	1754 Tryon Rd	Tryon Rd	DWM did repairs to the water or sanitary in the residents yard, they removed the granite curb. They will need to reset the granite curb.		It has been repaired.
23000298	4/11/2023	2/15/2023	1441 Lanier Manor	Lanier Manor	A cut in the road and the beauty strip was made for repairs to the water service line to this property on October 12th of 2022.		It has been repaired.

223 Total Loc	cations Requirin	ng DWM Repairs	(DWM Work Orders)	195 Known DWM Work	Orders Completed, 8/20-Present	28 Locations with Road Plates Covering Needed Repair		
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES	
23017344	4/25/2023	2/22/2023	1546 Windsor Pkwy	Windsor Pkwy	A depression has formed above the sanitary sewer service line to this property. It is 2 feet wide and 3 inches deep and it extends towards the sidewalk.		Repaired by the PW Dept.	
	1/9/2023	10/4/2022	2430 Coosawattee Dr	Coosawattee Dr	A sinkhole has developed in the beauty strip. The nearest utility is the sanitary sewer and we have reported it to DWM for further inspection		The sinkhole was repaired by OPTECH with WO 8673	
21048724 22023281	1/17/2023	5/24/2021 3/14/2022	1855 Tobey Rd NE	Tobey Rd NE	A sinkhole formed 6-ft deep, 6-ft in length, and, 4 -feet wide underneath the road in line with the sanitary sewer line from this property to the middle of the road. The sinkhole was repaired with WO 21048724. It was noted on 3/11/2022 that it had reopened and no concrete cap was installed on the trench.		Inspected 1/17/23 completed,	
22072849	1/23/2023	11/14/2022	2968 Cravenridge Dr.	Cravenridge Dr.	The crosswalk to the Ashford Park Elementary School was removed and damaged by DWM during maintenance to the water main. The sidewalk at the end of the crosswalk was partially repaired with asphalt including the trip hazards.		The sidewalk is being repaired by OPTECH with WO 8702.	
	1/24/2023	8/24/2022	1697 Wawona Terrace	Wawona Terrace	Emergency repairs for a water main break. The repairs to the road and landscaping are scheduled to be completed by 8/26/22		Inspected 1/24/23 completed.	
	1/24/2023	10/31/20222	1855, 1861 Dresden Dr	1861 Dresden Dr	Residents reported DWM completed sanitary sewer work but the shoulder is sinking.		Inspected 1/24/23 no change.	
22036495	1/30/2023	4/28/2022	3847 Granger Dr	Granger Dr	The concrete collar of manhole # 18-325-s130 is broken and is causing the road to break around it.		The repairs to the catch bsain is being done by Corbett.	
2063959	2/2/2023	8/19/2020	4180 4352 4368 Berkford Circle	4352 4368 Berkford Circle	A depression in the road 3-inches deep formed last year and no repairs have been made. First reported on 8/29/2020.		Repairs have been completed	
21069929	2/3/2023	8/3/2021	1514 Ragley Hall Rd NE	Ragley Hall Rd NE	A depression formed underneath the sidewalk. The sidewalk collapsed 3- inches above the sanitary and water service lines to this property.		Repairs have been completed	

223 Total Loo	cations Requirin	ng DWM Repairs	(DWM Work Orders)	195 Known DWM Work	Orders Completed, 8/20-Present	28 Locations w	vith Road Plates Covering Needed Repair
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
21091053	2/3/2023	9/28/2021	2332 Drew Valley Rd	Drew Valley Rd	There is a large depression over the sanitary sewer service line in the middle of the road.		Repairs have been completed
21094283	2/3/2023	10/12/2021	3882 Ashford Dunwoody Rd	Ashford Dunwoody Rd	DWM made repairs to a water main break and damaged the sidewalk at both ends and behind of it. The water break caused the sidewalk to sink before the catch basin creating a trip hazard. DWM has to demo and repair the sidewalk. The repairs were made the first week of October.		
22001232	2/3/2023	1/11/2022	2638 Drew Valley Rd	Drew Valley Rd	Repairs to a water valve and water main were made and it damaged the ADA ramp. The water valve was left above the surface of the road.		Repairs have been completed
22037156	2/3/2023	5/2/2022	1310 Ragley Hall Rd	Ragley Hall Rd	Two depressions in the road have been observed. One is across a water leak and above the SS and the other is above the SS main near manhole # 18- 302-s066.		Repairs have been completed
	2/3/2023	10/4/2022	2420 Drew Valley Rd	Drew Valley Rd	The shoulder of the road, granite curbs, and pavement were disturbed for repairs to the water main and the service line to this property. Mulch was installed but no other repairs made.		Repairs have been completed
22083979	2/3/2023	10/13/2022	1414 Ragley Hall Dr	Ragley Hall Dr	3 sections of the sidewalk were removed for repairs to the water main. GAB was added, and seed and straw to the shoulder and beauty strip.		Repairs have been completed
22016627 СОВ	2/10/2023	2/22/2022	2925 Skyland Dr	Skyland Dr	A sinkhole has developed at the edge of the road with the granite curb in line with the water service line to this property. DWM has stated the sinkhole not related to the water main underneath of it.		Inspected 9/15/2022, PW called Atl. Gas& light to check for a possible gas leak, nothing was found. Will notify the owner of what was found. The homeowner will repaired it.
22071998	2/10/2023	8/19/2022	4279 Ashwoody Trl NE	Ashwoody Trl NE	There is a large amount of water flow from the water meter at this property flowing into the road and the stormwater is equivalent to 5 gallons per minute.		The repairs have been completed.
22084419	2/10/2023	9/23/2022	4082 Nancy Creek Way	Nancy Creek Way	Emergency repairs to the water service line to this property were made on 9/22/22. Mud and sediments were left on the road and in the stormwater conveyance system.		The repairs to the shoulder have been completed and the road is clean.

223 Total Loo	cations Requirin	ng DWM Repairs	(DWM Work Orders)	195 Known DWM Work	Orders Completed, 8/20-Present	28 Locations w	ith Road Plates Covering Needed Repair
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
	2/10/2023	10/4/2022	1583 Fearn Circle	Fearn Circle	Repairs to a water service lateral to this property were completed but not all the sod was installed.		The landscape has been completed
21062135	3/8/2023	7/12/2021 1/18/2022	2622 Briarcliff Rd NE	Briarcliff Rd NE	Pothole has opened up once more due to contact water spewing from it. First reported on 7/12/21. The City of Brookhaven Street crew repaired only the pothole due to the delay by DWM responding to our SR. A second SR has been submitted on 10/6/21. DWM has excavated the pothole and installed a road plate.	x	The cuts in the road have been repaired.
22059814	3/21/2023	7/12/2022	1448 1457 1466 Grant Dr.	1457 1466 Grant Dr.	A large depression has formed in the road above the sanitary sewer main and where the service line to this property is located.		The concrete cap plus the repairs to the road have been completed by A&S Paving, a subcontractor for DWM.
	3/21/2023	9/22/2022	2297 Nesbitt Dr	Nesbitt Dr	A trench to the middle of the road has been made and an excess amount of GAB added to it. The GAB has created a hump in the street. Additionally, the shoulder of the road was disturbed and has not been repaired.		The concrete cap plus the repairs to the road have been completed by A&S Paving, a subcontractor for DWM.
22097532	3/21/2023	11/21/2022	2455 Ellijay Dr.	Ellijay Dr.	DMW purform a point repair that had been reported by the homeowner.		The concrete cap plus the repairs to the road have been completed by A&S Paving, a subcontractor for DWM.
	3/21/2023	1/12/2023	2396 Coosawattee Dr.	Coosawattee Dr.	Water has been found entering the stormwater pipe underneath the road at a constant flow rate. Unable to determine the location of the leak, we have contacted DWM to investigate the water service lateral to 2395 Coosawattee Dr.		The road has been repaired by A&S Paving. A contractor for DWM.
23020563	3/23/2023	3/6/2023	3193 LeConte Ave.	LeConte Ave.	A new concrete curb and gutter were built by the PW Dept. at the intersection of Inman Dr and LeConte Ave. A DWM truck responding to an emergency water leak at 3180 LeConte Ave run over the curb breaking it in three places. The DWM supervisor, Theodore Travis was on the scene and was provided with pictures of the incident.		Repaired by Optech
22060218 22082176	3/28/2023	7/8/2022 9/1/2022 2/13/2023	3308 Finistere Ct	Finistere Ct	A 3x3 and 8 inches deep sinkhole has formed over the water service line to this property. The City isntalled cones and a barrel with caution and a request was made to DWM to install a road plate.		The road has been repaired.

223 Total Loc	ations Requirin	ng DWM Repairs	(DWM Work Orders)	195 Known DWM Work	Orders Completed, 8/20-Present	28 Locations w	vith Road Plates Covering Needed Repair
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
22073233 22100092	4/10/2023	8/16/2022 11/22/2022	2572 Apple Valley Rd	Apple Valley Rd	A 4-FT deep sinkhole has formed at the edge of the concrete sidewalk near the sanitary sewer service line and between the cleanup and the manhole in the middle of the street.	х	The road has been repaired.
22088465 22091310	4/10/2023	9/15/2022 2/10/2023	3192 Caldwell Rd.	Caldwell Rd.	DWM did an emergency repair on the sanitary lateral, they backfilled with GAB. There is no plate over the hole.		The road has been completely repaired.
21117119	4/10/2023	9/20/2022	1970 E Roxboro Rd.	E Roxboro Rd.	Repairs were made to a DWM pipe, they placed a steel plate over the hole.	х	The road has been completely repaired on 4/10/2023
23007895	4/10/2023	12/21/2022	1300 Hermance Dr	Hermance Dr	Repairs to the water main were conducted by DWM. The northbound lane was removed and GAB was added to the trench. Rain events have continuously washed away		The road has been completely repaired on 4/10/2023
	4/10/2023	4/6/2023	1661 Tryon Rd	Tryon Rd	Road repairs are underway by A&S Paving		The road has been completely repaired on 4/10/2023
	5/16/2023	9/22/2022	1518 Grant Dr	Grant Dr	A depression has developed on a patch previously repaired by the City.		
	6/5/2023	3/8/2023	3901 Ashford Dunwoody Rd	Ashford Dunwoody Rd	Approximately 30 feet of the sidewalk have been damaged or removed for repairs to the water main. GAB has been added to the removed sections of the sidewalk.	х	The sidewalk has bee repaired.
23010654	6/8/2023	2/8/2023	2012 E Roxboro Rd	E Roxboro Rd	A metal plate was installed for repairs to the water main. The plate shifted and motorists are avoiding it by driving on the opposite lane	х	Street repairs completed on 6/8/23
	6/8/2023	6/6/2023	3929 Ashford Dunwoody Rd	Ashford Dunwoody Rd	Road plates have been placed over recent emergency repairs by DWM	x	Street repairs completed on 6/8/23
	6/14/2023	9/15/2022	1314 Beech Haven Dr	Beech Haven Dr	A water service line has hit and is leaking at the enttrance to the park. DWM came out and dug up two locations but did not repair the leak. They covered the holes with GAB. Water is running into the street.		Repaired by A&S Paving

223 Total Loo	cations Requirir	ng DWM Repairs	(DWM Work Orders)	195 Known DWM Work	Orders Completed, 8/20-Present	28 Locations w	ith Road Plates Covering Needed Repair
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
23048393	6/20/2023	6/20/2023	3251 Breton Circle	Breton Circle	A depression has been forming at the intersection of Breton Circle and Woodrow Way. The City of Brookhaven has twice in the past, added pavement level with the street, and has continued to drop. Depression is		An inspection by DWM Water found no leakage however it was found a probable sanitary sewer failure. Will report it under 3262 Woodrow Way
22052846	6/27/2023	6/17/2022	2794 Ashford Rd	Ashford Rd	A sinkhole has developed next to repairs made by DWM to another sinkhole at 2791 Ashford Rd.		Repairs have been completed
22075222 22103460	6/27/2023	8/23/2022 1/30/2023	2791 Ashford Rd	Ashford Rd	Under the previous repairs for DWW WO 21079815, the sewer laterals for 2791 and 2794 were repaired but the COB or Dekalb Trench Standards were not followed. A benched concrete cap was not installed and the road was not milled and paved from BOC to BOC. The road has begun to sink		Inspected on 6/5/23. Pending repair schedule from DWM
23000654	6/27/2023	1/17/2023	2929 Surrey Ln	Surrey Ln	DWM performed a repair to the sanitary line, tyhey bckfilled the hole with 57 stone and GAB. There is no road plate and the stones and GAB is washing out down the street.		Inspected 1/17/23
23010194	6/27/2023	2/15/2023	1861 Tobey Rd	Tobey Rd	A cut in the road was made for repairs to the sanitary sewer lateral to this property. GAB was added and some has washed away.		
	7/10/2023	1/12/2023	2271 Fairway Circle	Fairway Circle	The driveway and the shoulder of the road have been removed for repairs to the water main.		The repairs have been completed.
23035233	7/10/2023	5/17/2023	3268 Breton Circle	Breton Circle	A cut to the middle of the road was made for repairs to the sanitary sewer service line to this property. GAB was added to the trench.		The paving has been completed.
22018437	7/13/2023	2/28/2022	2367 Ewing Dr	Ewing Dr	A sinkhole has formed underneath the concrete cap installed by DWM.		The old line is to be abandoned and replaced with a new line later this year by DWM.
22018437	7/13/2023	2/28/2022	2373 Ewing Dr	Ewing Dr	A sinkhole has formed underneath the concrete cap installed by DWM.		The old line is to be abandoned and replaced with a new line later this year by DWM.
22036023	7/13/2023	4/26/2022	4166 Candler Lake W	Candler Lake W	3 depressions have formed above the SS main which have caused the entire road to further break.		The depression will be repaired with the street pavement repairs scheduled for 2024 by the COB

223 Total Loo	cations Requirin	ng DWM Repairs	(DWM Work Orders)	195 Known DWM Work	Orders Completed, 8/20-Present	ers Completed, 8/20-Present 28 Locations with Road Plates Covering Needed Repair		
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES	
22036023	7/13/2023	4/26/2022	4128 Candler Lake W	Candler Lake W	A large depression has formed in the middle of the road above the SS mainline. The depression is in line with the SS service line to this property.		The depression will be repaired with the street pavement repairs scheduled for 2024 by the COB	
22036028	7/13/2023	4/26/2022	4046 Candler Lake W	Candler Lake W	A large depression has formed from the curb to the middle of the road. A locate811 has been requested as this depression may be water or sewer.		The depression will be repaired with the street pavement repairs scheduled for 2024 by the COB	
22082319	7/13/2023	9/14/2022	2933 Parkridge Dr	Parkridge Dr	A minor water leak around the water meter has caused the granite curbs to collapse. Due to the slope of the front yard, the water is traveling underneath the granite curbs. We have replaced some granite curbs and will wait for DWM to investigate the leak before completing our repairs.		The leak has stopped and the granite curbs have not collapsed. 7/13/2023	
22089511	7/13/2023	10/12/2022	2765 Osborne Rd	Osborne Rd	A water leak underneath the driveway to this property was reported to DWM.		The leak has been repaired.	
	7/13/2023	10/13/2022	3505 Hampton Hall Way	Hampton Hall Way	DWM repair the water main on the shoulder of the road. The shoulder has not been restored.		The shoulder has been restored.	
	7/13/2023	10/24/2020	1247 Oostanula Dr	Oostanula Dr	The driveway and part of the road were removed for repairs to the water main and lateral to this home. GAB was added to the driveway and mud was not removed from the road.		The driveway and pavement have been repaired.	
	7/13/2023	1/12/2023	3298 Osborne Rd	Osborne Rd	Failure of a previous repair under WO 22086487 has caused the front yard to collapsed		The shoulder of the street has been repaired.	
23010658	7/13/2023	2/8/2023	2065 Brook Forest Dr	Brook Forest Dr	A Sinkhole has formed in the road in line with the water service to this property.		The sinkhole has been repaired.	
23028165	7/13/2023	4/3/2023	1426 Kendrick Rd	Kendrick Rd	A crack in the road traversing the sanitary sewer manhole has appeared.		DWM inspected and found no issues.	

223 Total Locations Requiring DWM Repairs (DWM Work Orders)				195 Known DWM Work Orders Completed, 8/20-Present			28 Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES	
21063205	7/13/2023	7/15/2021	1896 E Roxboro Rd NE	E ROXDORO Rd NE	Work on fire hydrant. Tree on the sidewalk and sinkhole at edge of it. DWM cones installed. There is a small sinkhole next to the fire hydrant.		The shoulder of the road has been repaired.	
22046688	7/20/2023	5/27/2022 4/10/2023	3707 Lambert Ln	I amhert I n	The original sinkhole was repaired by the COB PW. Another sinkhole has formed in the road 4 times larger than the original	X	To be repaired by A&S Paving. No scheduled has been provided. 7/13/2023	