in

Brookhaven Rights-of-Way February 2024

231 Total DWM Work Orders Created

				,, ,				
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES	
21085424		9/14/2021 4/3/2023	4560 E Brookhaven Dr	E Brookhaven Dr	Large depression has formed in the middle of the road near the sanitary sewer line.		Two other depressions over the sanitary sewer main and laterals have formed. Inspected on 7/13/2023	
21091564 22001249 23012287		10/1/2021 01/13/2022	2484 Oostanaula Dr. NE	Oostanaula Dr. NE	The road has been poorly repaired with no concrete cap. The entire asphalt patch is sinking.		Inspected on 11/2/2023	
22011262		2/1/2022	1451 Sylvan Circle	Sylvan Circle	A depression has formed in the middle of the road along with the sanitary sewer mainline. The depression is approximately 6-ft long by 3-ft wide and 3-inches deep.		Inspected 11/7/2023 the repair has not been completed.	
22015961		2/18/2022	1537 Aragon Way	Aragon Way	In the middle of the road above the Sanitary Sewer line and at the edge of a trench the road is sinking.		Inspected on 11/2/2023	
		9/1/2022	1285 Old Johnson Ferry Rd	Old Johnson Ferry Rd	The ADA ramp has been removed for repairs to the water main. GAB was installed but not safety cones or caution tape. The GAB has a washout at the edge with the pavement creating dangerous conditions for pedestrians.		A valve was installed in the ADA ramp area and a ramp was poured back around the water valve. This does not comply with ADA codes, the valve has to be relocated. 11/14/2022	
23012449		2/13/2023	2827 N. Thompson Rd.	N. Thompson Rd.	There is a deep depression forming to the right of the driveway. A previous DWM sanitary sewer repair is sinking in front of the driveway.		The street paving is to be repaired by AS Paving. No schedule has yet been provided.	
22097416		11/14/2022	1242 Goodwin Rd	Goodwin Rd	A depression in the road has developed. The depression has developed above the sanitary sewer lateral.	х	Inspected on 11/2/2023	
22092740 22093845		11/18/2022	1536 Trentwood Pl	Trentwood PI	Water main repairs in front of this property were made by DWM. Left to repair is the landscaping, granite curbs and the road.		Updated on 11/2/2023	
		1/23/2023	3517 Ashford Dunwoody RD NE	Ashford Dunwoody RD NE	There are various potholes made to uncover water valves near the park. These have not been raised creating dangerous conditions for drivers and cyclists.		Inspected on 2/7/2024	

in

Brookhaven Rights-of-Way February 2024

231 Total DWM Work Orders Created

DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
23020321		3/2/2023	2573 Skyland Trail	Skyland Trail	3 large sinkholes and a small one have formed above and in front of the water main alongside the frontage of this property.		
23028044		4/3/2023	1190 Pine Grove Ave	Pine Grove Ave	A large depression on the asphalt has formed from the edge of the paving to the sanitary sewer manhole.		Insspected on 7/13/2023. No repairs have been completed.
23029788		4/6/2023	3273 Stratfield Dr	Stratfield Dr	A long depression has from 3280 to 3273 above the sanitary sewer main and between two manholes and Lift Station #50		Inspected on 7/13/2023. No repairs have been completed.
24040494 24003109		5/16/2023	4006 E Brookhaven Dr	E Brookhaven Dr	A four-foot by two-foot wide sinkhole has formed in front of this property DW. A safety cone has been installed over the sinkhole. DWM will repair the sinkhole.		Inspected on 12/8/2023. No repairs have been completed.
23052473		7/11/2023	2864 Duncan Dr	Duncan Dr	The sinkhole was repaired by DWM and the street pavement. Left to be completed is the shoulder restoration.		Inspected 1/4/2024
23059186		8/8/2023	1217 Kendrick Rd	Kendrick Rd	During the recent storm events, a large depression/sinkhole has formed above the sanitary sewer main. It is 6 feet long by 3 feet wide and continues to grow. A few feet from the depression, a crack in the street from curb to curb has formed. It continues to the shoulder at 1220 Kendrick Rd where	Х	
		9/18/2023	1770 Duke Rd	Duke Rd	Repairs to the water main underneath the driveway to this property were completed last week. GAB was installed on the driveway. The street was severely compromised during the water break and repairs. At least half of the street must be milled and paved.		Has yet to be repaired. Inspected on 1/3/24
23073739 23073740		11/2/2023	1158 W Nancy Creek Dr	W Nancy Creek Dr	A water leak underneath the driveway of this property was repaired. A new driveway and two sections of the sidewalk were installed. However, the new driveway slope is 4 and 5% which does not meet ADA requirements.		Inspected on 1/3/24
23027989		4/3/2023	3292 Buford HWY	Buford HWY	On the N Cliff Valley Way side of the AMR building. The shoulder has yet to be repaired by DWM.		Inspected on 11/7/2023.

in

Brookhaven Rights-of-Way February 2024

231 Total DWM Work Orders Created

				200 Miletin Portin Work Gracies completed, 9/20 Miletin				
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES	
21105504 23062530		11/2/2023	1082 Mendell Circle	Mendell Circle	A sinkhole has developed next to a previous DWM street repair.			
23094219		12/18/2023	1093 W Nancy Creek Dr	W Nancy Creek Dr	A sinkhole has formed near the center of the street and the SS main. PW investigated and found a sinkhole underneath the street. A temporary patch was installed and DWM notified.			
		12/15/2023	1850 Tobey Rd	Tobey Rd	A sinkhole has formed in the middle of the street above the SS main.	Х	Inspected on 1/4/2024	
24003372		1/17/2024	2743 Redding Rd	Redding Rd	A large depression has developed above the SS in the middle of the street.			
24003366		1/17/2024	2403 Coosawattee Dr	Coosawattee Dr	A depression has developed on a previous DWM pavement repairs.			
24003537			1075 Lynmoor Dr	Lynmoor Dr	A large depression has developed above a previous SS repair.			
2059434 2059640 23082146		8/7/2020 10/30/2023	1462 Brawley Circle	Brawley Circle	A depression above the sanitary sewer main developed early last year. This was previously reported, however, no work has ever been observed to repair the pavement. Please send a crew to investigate and make the necessary repairs. Remember that poor compaction at the time the		Last reported on 1/19/2024	
22018437		2/28/2024	2373 Ewing Dr.	Ewing Dr.	The length of the concrete cap installed by DWM over 12 years ago over the water main is collapsing due to poor compaction and not being installed to the Dekalb Watershed trench details standards. The entire concrete cap has to be removed. The trench soils have to be tested and properly compacted. The concrete cap repair following the City of Brookhaven Trench details as it is being done for the new water main on Drew Valley Rd.			
24003372			2743 Redding Rd	Redding Rd	A large depression has formed above the SS main in the middle of the street.			
24019882		2/28/2024	1754 Duke Rd	Duke Rd	The ADA ramp has been removed for repairs to the water main. GAB was installed but not safety cones or caution tape. The GAB has a washout at the edge with the pavement creating dangerous conditions for pedestrians.			
24019790		2/28/2024	1097 Oxford Crescent NE	Oxford Crescent NE	A sinkhole has developed above the sanitary sewer line. A safety barrel has been installed above it.	Х		

in

Brookhaven Rights-of-Way February 2024

231 Total DWM Work Orders Created

DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
24003366			2403 Coosawattee Dr	Coosawattee Dr	A previous DWM SS repair is sinking.		
22057005	2/14/2024	7/1/2022 6/27/2023	4040 Peachtree Rd NE	Peachtree Rd NE	The repair was done on East Brookhaven Rd. in front of Dunkin Donuts. New problems were reported and a road plate was installed over 9 months ago	х	The street repairs have been completed.
23404374	2/14/2024	6/6/2023	1271 Star Dr	Star Dr	A 6 feet long by 4 feet wide sinkhole has formed on the street above this property's sanitary sewer service line. DWM has repair the sinkhole and added GAB to the trench.		The street repairs have been completed.
	2/7/2024	11/2/2023	1050 Capital Club Circle	Capital Club Circle	On the week prior to October 23rd, DWM responded to a water leak request submitted by Hyper Networks at this location. The front yard of this property was severely damaged and not properly restored.		The front and side yard have been repaired.
	1/25/2024	11/7/2023	2753/2748 S Bamby Ln	S Bamby Ln	A water service work was completed at this location and a road plate was installed across the street at 2748 S Bamby Ln. The receipt number for this work is 23069884.	X	The street has been repaired.
23020683	1/2/2024	4/6/2023	3320 Woodrow Way	Woodrow Way	Cuts to the road and shoulder were made for repairs to the sanitary sewer lateral to this property. The trench was repaired with GAB and no road plates have been installed		Paving and the shoulder have been completed.