in

Brookhaven Rights-of-Way April 2024

238 Total DWM Work Orders Created

| DWM WO | Observed Completion Date | Reported Date | ADDRESS | Street | DESCRIPTION | Road Plate Used | UPDATES |
|----------------------------------|--------------------------------|------------------------------------|----------------------------|----------------------|--|--------------------|---|
| 21085424 24033585 24039571 | | 9/14/2021 4/3/2023 4/11/2024 | 4560, 4588 E Brookhaven Dr | 4588 E Brookhaven Dr | A large depression has formed in the middle of the road near the sanitary sewer line. A sinkhole has formed around the manhole on the cul-de-sac. | | Two other depressions over the sanitary sewer main and laterals have formed. Inspected on 4/11/2024 |
| 21091564 22001249 23012287 | | 10/1/2021 01/13/2022 | 2484 Oostanaula Dr. NE | Oostanaula Dr. NE | The road has been poorly repaired with no concrete cap. The entire asphalt patch is sinking. | | Inspected on 3/15/2024 |
| 22011262 24030116 | | 2/1/2022 3/19/2024 | 1451, 1456 Sylvan Circle | 1456 Sylvan Circle | A depression has formed in the middle of the road along with the sanitary sewer mainline. The depression is approximately 6-ft long by 3-ft wide and 3-inches deep. | | Inspected 4/11/2024 the repair has not been completed. |
| 22015961 | | 2/18/2022 | 1537 Aragon Way | Aragon Way | In the middle of the road above the Sanitary Sewer line and at the edge of a trench the road is sinking. | | Inspected on 11/2/2023 |
| | | 9/1/2022 | 1285 Old Johnson Ferry Rd | Old Johnson Ferry Rd | A valve was installed in the ADA ramp area and a ramp was poured back around the water valve. This does not comply with ADA codes, the valve has to be relocated. 11/14/2022 | | Inspected on 3/12/2024 |
| 22097416 | | 11/14/2022 | 1242 Goodwin Rd | Goodwin Rd | A depression in the road has developed. The depression has developed above the sanitary sewer lateral. | Х | Inspected on 3/15/2024 |
| 23020321 | | 3/2/2023 | 2573 Skyland Trail | Skyland Trail | 3 large sinkholes and a small one have formed above and in front of the water main alongside the frontage of this property. | | Inspected on 3/14/2024 |
| 23028044 24028753 | | 4/3/2023 3/15/2024 | 1190 Pine Grove Ave | Pine Grove Ave | A large depression on the asphalt has formed from the edge of the paving to the sanitary sewer manhole. This has continue to dropped. | | Insspected on 3/15/2024. No repairs have been completed. |
| 23029788 | | 4/6/2023 | 3273 Stratfield Dr | Stratfield Dr | A long depression has from 3280 to 3273 above the sanitary sewer main and between two manholes and Lift Station #50 | | Inspected on 3/12/2024. No repairs have been completed. |

in

Brookhaven Rights-of-Way April 2024

238 Total DWM Work Orders Created

| DWM WO | Observed Completion Date | Reported Date | ADDRESS | Street | DESCRIPTION | Road Plate Used | UPDATES |
|----------------------|--------------------------------|---------------|-----------------------|------------------|---|--------------------|-------------------------|
| | | 9/18/2023 | 1770 Duke Rd | Duke Rd | Repairs to the water main underneath the driveway to this property were completed last week. GAB was installed on the driveway. The street was severely compromised during the water break and repairs. At least half of the street must be milled and paved. | | Inspected on 2/27/24 |
| 23073739 23073740 | | 11/2/2023 | 1158 W Nancy Creek Dr | W Nancy Creek Dr | A water leak underneath the driveway of this property was repaired. A new driveway and two sections of the sidewalk were installed. However, the new driveway slope is 4 and 5% which does not meet ADA requirements. | | Inspected on 1/3/24 |
| 23084017 | | 11/7/2023 | 3188 Inman Dr | Inman Dr | The road is caving in above the sanitary sewer main. | | Inspected on 1/3/24 |
| 23027989 | | 4/3/2023 | 3292 Buford HWY | IBUTORO HWY | On the N Cliff Valley Way side of the AMR building. The shoulder has yet to be repaired by DWM. | | Inspected on 11/7/2023. |
| 21105504 23062530 | | 11/2/2023 | 1082 Mendell Circle | Mendell Circle | A sinkhole has developed next to a previous DWM street repair. | | |
| 23094219 | | 12/18/2023 | 1093 W Nancy Creek Dr | W Nancy Creek Dr | A sinkhole has formed near the center of the street and the SS main. PW investigated and found a sinkhole underneath the street. A temporary patch was installed and DWM notified. | X | Inspected on 3/15/2024 |
| | | 12/15/2023 | 1850 Tobey Rd | Tobey Rd | A sinkhole has formed in the middle of the street above the SS main. | X | Inspected on 1/4/2024 |
| 24003372 | | 1/17/2024 | 2743 Redding Rd | Redding Rd | A large depression has developed above the SS in the middle of the street. | | Inspected on 1/17/2024 |

in

Brookhaven Rights-of-Way April 2024

238 Total DWM Work Orders Created

| DWM WO | Observed Completion Date | Reported Date | ADDRESS | Street | DESCRIPTION | Road Plate Used | UPDATES |
|--------------------------------|--------------------------------|------------------------|-------------------------|--------------------|---|--------------------|--|
| 24003537 24005566 | | 1/16/2024 3/15/2024 | 1075 Lynmoor Dr | Lynmoor Dr | A large depression has developed above a previous SS repair. DWM has performed repairs on the street and filled the trench with GAB. Recent rain events has washed out some of the GAB near the granite curbs. | | AS Paving will complete the street repairs. The street repairs are scheduled for 4/12/2024 and 4/16/2024 |
| 2059434 2059640 23082146 | | 8/7/2020 10/30/2023 | 1462 Brawley Circle | Brawley Circle | A depression above the sanitary sewer main developed early last year. This was previously reported, however, no work has ever been observed to repair the pavement. Please send a crew to investigate and make the necessary repairs. Remember that poor compaction at the time the | | Last reported on 1/19/2024 |
| 22018437 | | 2/28/2024 | 2373 Ewing Dr. | Ewing Dr. | The length of the concrete cap installed by DWM over 12 years ago over the water main is collapsing due to poor compaction and not being installed to the Dekalb Watershed trench details standards. The entire concrete cap has to be removed. The trench soils have to be tested and properly | | Inspected on 3/15/2024 |
| 24003372 | | 1/13/2024 | 2743 Redding Rd | Redding Rd | A large depression has formed above the SS main in the middle of the street. | | Inspected on 4/11/2024 |
| 24019882 | | 2/28/2024 | 1754 Duke Rd | Duke Rd | The ADA ramp has been removed for repairs to the water main. GAB was installed but not safety cones or caution tape. The GAB has a washout at the edge with the pavement creating dangerous conditions for pedestrians. | | Inspected on 2/27/2024. The shoulder of the road has been repaired. |
| 24019790 | | 2/28/2024 | 1097 Oxford Crescent NE | Oxford Crescent NE | A sinkhole has developed above the sanitary sewer line. DWM has made initial repairs and installed a road plate | | The street repairs have been scheduled for 4/12/2024 and 4/16/2024 |
| | | 3/11/2024 | 1200 Parkside PL | Parkside PL | A water leak was repaired and one road plate was installed. However, the trench is wider than the trench. | х | The street will be repaired by AS Paving. The street repairs are scheduled for 4/12/2024 and 4/16/2024 |
| 24033841 | | 3/27/2024 | 1483 Grant Dr | Grant Dr | A depression across the street has formed which could be water or sanitary sewer related. | | |

in

Brookhaven Rights-of-Way April 2024

238 Total DWM Work Orders Created

| DWM WO | Observed Completion Date | Reported Date | ADDRESS | Street | DESCRIPTION | Road Plate Used | UPDATES |
|----------|--------------------------------|---------------|----------------------|-----------------|--|--------------------|---------------------------------------|
| 24033868 | | 3/28/2024 | 1161 Victoria St | | A previously repaired SS service line by DWM is failing. The concrete gutter and part of the driveway have sunk. | | |
| 24029694 | | 3/26/2024 | 2834 Duncan Dr | | A deep sinkhole has developed at the water meter and towards the middle of the street. | | |
| 24003949 | | 4/10/2024 | 2806 Redding Rd | | At the request of the property owner, DWM cut open the street for repairs to the SS service line. | | |
| 24003366 | | 1/17/2024 | 2403 Coosawattee Dr | Coosawattee Dr | A previous DWM SS repair is sinking. | | |
| PW Dept | 4/11/2024 | 5/16/2023 | 4006 E Brookhaven Dr | E Brookhaven Dr | A four-foot by two-foot wide sinkhole has formed in front of this property DW. A safety cone has been installed over the sinkhole. DWM will repair the sinkhole. | | The PW Dept will repair the sinkhole. |
| 24028416 | 4/11/2024 | 3/22/2024 | 1421 Brairwood Rd | Brairwood Rd | 10 Ft of the sidewalk was removed for water service line repairs. | | The sidewalk has been repaired. |

in

Brookhaven Rights-of-Way April 2024

238 Total DWM Work Orders Created

| DWM WO | Observed Completion Date | Reported Date | ADDRESS | Street | DESCRIPTION | Road Plate Used | UPDATES |
|----------------------|--------------------------------|-----------------------|-----------------------------|------------------------|---|--------------------|--|
| 24037484 | 4/10/2024 | 4/5/2024 | 2790 Redding Rd | Redding Rd | A sinkhole has formed on the shoulder of the street exposing the water main. | | The shoulder of the street has been repaired. |
| 23059186 | 4/5/2024 | 8/8/2023 | 1217 Kendrick Rd | Kendrick Rd | During the recent storm events, a large depression/sinkhole has formed above the sanitary sewer main. It is 6 feet long by 3 feet wide and continues to grow. A few feet from the depression, a crack in the street from curb to curb has formed. It continues to the shoulder at 1220 Kendrick Rd where another sinkhole is forming. | х | The PW Dept. will repair the street. |
| 23052473 | 3/27/2024 | 7/11/2023 | 2864 Duncan Dr | Duncan Dr | The sinkhole was repaired by DWM and the street pavement. Left to be completed is the shoulder restoration. | | The shoulder has been repaired by the homeowner. |
| 22092740 22093845 | 3/15/2024 | 11/18/2022 | 1536 Trentwood Pl | Trentwood Pl | Water main repairs in front of this property were made by DWM. The landscape has been completed | | Inspected on 3/15/2024 |
| 23012449 | 3/15/2024 | 2/13/2023 | 2827 N. Thompson Rd. | IN Thompson Rd | There is a deep depression forming to the right of the driveway. A previous DWM sanitary sewer repair is sinking in front of the driveway. | | The street was repaired on 3/13/2024 |
| | 3/15/2024 | 1/23/2023 | 3517 Ashford Dunwoody RD NE | Ashford Dunwoody RD NE | There are various potholes made to uncover water valves near the park. These have not been raised creating dangerous conditions for drivers and cyclists. | | Inspected on 3/15/2024. |
| 22057005 | 2/14/2024 | 7/1/2022 6/27/2023 | 4040 Peachtree Rd NE | | The repair was done on East Brookhaven Rd. in front of Dunkin Donuts. New problems were reported and a road plate was installed over 9 months ago | х | The street repairs have been completed. |
| 23404374 | 2/14/2024 | 6/6/2023 | 1271 Star Dr | | A 6 feet long by 4 feet wide sinkhole has formed on the street above this property's sanitary sewer service line. DWM has repair the sinkhole and added GAB to the trench. | | The street repairs have been completed. |
| | 2/7/2024 | 11/2/2023 | 1050 Capital Club Circle | Capital Club Circle | On the week prior to October 23rd, DWM responded to a water leak request submitted by Hyper Networks at this location. The front yard of this property was severely damaged and not properly restored. | | The front and side yard have been repaired. |

in

Brookhaven Rights-of-Way April 2024

238 Total DWM Work Orders Created

| DWM WO | Observed Completion Date | Reported Date | ADDRESS | Street | DESCRIPTION | Road Plate Used | UPDATES |
|----------|--------------------------------|---------------|----------------------|-------------|---|--------------------|--|
| | 1/25/2024 | 11/7/2023 | 2753/2748 S Bamby Ln | S Bamby Ln | A water service work was completed at this location and a road plate was installed across the street at 2748 S Bamby Ln. The receipt number for this work is 23069884. | X | The street has been repaired. |
| 23020683 | 1/2/2024 | 4/6/2023 | 3320 Woodrow Way | Woodrow Way | Cuts to the road and shoulder were made for repairs to the sanitary sewer lateral to this property. The trench was repaired with GAB and no road plates have been installed | | Paving and the shoulder have been completed. |