215 Total Locations Requiring DWM Repairs (DWM Work Orders)	169 Known DWM Work Orders Completed, 8/20-Present	25 Locations with Road Plates Covering Needed Repair
Observed		

215 Total Locations Requiring DWM Repairs (DWM Work Orders)		169 Known DWM Work Orders Completed, 8/20-Present			25 Locations with Road Plates Covering Needed Repair		
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
21085424		9/14/2021 4/3/2023	4560 E Brookhaven Dr	E Brookhaven Dr	Large depression has formed in the middle of the road near the sanitary sewer line.		Two other depressions over the sanitary sewer main and laterals have formed. Inspected on 7/13/2023
21091564 22001249 23012287		10/1/2021 01/13/2022	2484 Oostanaula Dr. NE	Oostanaula Dr. NE	The road has been poorly repaired with no concrete cap. The entire asphalt patch is sinking.		Inspected on 7/13/2023
23011860		6/14/2022 2/10/2023	2002 Drew Valley Rd	Drew Valley Rd	There is a large depression over the sanitary sewer service line to this property.		Inspected on 7/13/2023
21023844 23037773		12/15/2021 8/7/2023	3246 Lynwood Dr	Lynwood Dr	A depression has formed over the sanitary sewer line. It is approximately 3 inches deep and it is happening on old road repairs. It seems to be the SS service line to this property. Repairs have been completed and GAB added to the trench.		Inspected 6/8/2023
22009036		1/28/2022	1865 Canmont Dr	Canmont Dr	A previously repaired patch near and around the DWM sanitary sewer manhole has dropped approximately 3-inches.		Inspected 1/24/23 no change.
22011262		2/1/2022	1451 Sylvan Circle	Sylvan Circle	A depression has formed in the middle of the road along with the sanitary sewer mainline. The depression is approximately 6-ft long by 3-ft wide and 3-inches deep.		Inspected 7/12/2023 the repair has not been done.
22015961		2/18/2022	1537 Aragon Way	Aragon Way	In the middle of the road above the Sanitary Sewer line and at the edge of a trench the road is sinking.		Inspected 9/16/2022, there has been no work done.
		2/18/2022	3012 Surrey Ln	Surrey Ln	The road is sinking from the middle of the road towards the water meter.		Inspected 1/17/23 no change, the road is still sinking.
22057005		7/1/2022 6/27/2023	4040 Peachtree Rd NE	Peachtree Rd NE	The repair was done on East Brookhaven Rd. in front of Dunkin Donuts. New problems were reported and a road plate was installed over 9 months ago	х	Inspected 7/13/2023

15 Total Locations Requiring DWM Repairs (DWM Work Orders)	169 Known DWM Work Orders Completed, 8/20-Present
.13 Total Locations Requiring Divivi Repairs (Divivi Work Orders)	103 Kilowii Dwivi Work Orders Collipieted, 8/20-Fresent

215 Total Locations Requiring DWM Repairs (DWM Work Orders)		169 Known DWM Work Orders Completed, 8/20-Present			25 Locations with Road Plates Covering Needed Repair		
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
		9/1/2022	1285 Old Johnson Ferry Rd	Old Johnson Ferry Rd	The ADA ramp has been removed for repairs to the water main. GAB was installed but not safety cones or caution tape. The GAB has a washout at the edge with the pavement creating dangerous conditions for pedestrians.		A valve was installed in the ADA ramp area and a ramp was poured back around the water valve. This does not comply with ADA codes, the valve has to be relocated. 11/14/2022
22072287		9/8/2022	1342 Old Johnson Ferry Rd	Old Johnson Ferry Rd	5 sections of the sidewalk have been removed for repairs to the water main. No cones or caution tape was used.		Updated on 1/23/2023. The beauty strip was not repaired. There is concrete on it and a gully has formed undermining the sidewalk and the granite curbs.
		9/15/2022	1348 N Cliff Valley Way		The lid for the water meter # 18-198-12064 has broken creating a dangerous trip hazard.		Inspected on 2/22/2023
		9/21/2022	3217 Mae Ave	Mae Ave	A water leak has been reported via an SR in the middle of the road. We have reported it to DWM. A cold patch was installed and no concrete cap.		inspected on 8/21/23
		9/20/2022	1257 Goodwin Rd	Goodwin Rd	In the intersection of Goodwin and Roxboro, there is a water valve lid missing.		
23012449		2/13/2023	2827 N. Thompson Rd.	N. Thompson Rd.	There is a deep depression forming to the right of the driveway. A previous DWM sanitary sewer repair is sinking in front of the driveway.		
22097416		11/14/2022	1242 Goodwin Rd	Goodwin Rd	A depression in the road has developed. The depression has developed above the sanitary sewer lateral.	Х	Inspected on 2/22/2023
22092708 22092740 22093845		10/15/2022	1536 Trentwood Pl	Trentwood Pl	Water main repairs in front of this property were made by DWM. Left to repair is the landscaping, granite curbs and the road.		Updated on 2/10/23
22108893		1/6/2022	3197 Lynwood Dr	Lynwood Dr	A 14-FT by 8-FT trench was made for repairs to the water main and GAB was added to the trench. Recent rain events have washed away the GAB which has been promptly repaired by DWM.		Inspected 3/6/2023

15 Total Locations Requiring DWM Repairs (DWM Work Orders)	169 Known DWM Work Orders Completed, 8/20-Present

213 TOTAL EUG	15 Total Locations Requiring DWINI Repairs (DWINI Work Orders) 169 Known L		103 KIIOWII DVVIVI WOIK	www.work.orders.completed, 8/20-Present		25 Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
22108893		1/6/2023	3215 Lynwood Dr	Lynwood Dr	A 3-FT by 3-FT trench has been made for repairs to the water main. The trench was filled with GAB.		Inspected 3/6/2023
		1/23/2023	3517 Ashford Dunwoody RD NE	Ashford Dunwoody RD NE	There are various potholes made to uncover water valves near the park. These have not been raised creating dangerous conditions for drivers and cyclists.		
		1/24/2023	1850 Canmont Rd.	Canmont Rd.	The sanitary line in this area of Canmont is failing causing the road to collaspe.		Inspected 1/24/23
		3/2/2023	2369 Winding Ln	Winding Ln	A depression is developing from the SS cleanout towards the road.		
23020321		3/2/2023	2573 Skyland Trail	Skyland Trail	3 large sinkholes and a small one have formed above and in front of the water main alongside the frontage of this property.		
23021770		3/9/2023	57 Executive Park South	Executive Park South	A trench made for the water service connection to the new apartment complex on 50 Executive Park South is sinking and the pavement next to it is as well.		
23027989		4/3/2023	1470 N Cliff Valley Way	N Cliff Valley Way	Water is bubbling next to the sidewalk. The water is flowing to a water vault owned by AT&T. AT&T has been notified of a sinkhole forming near their cabinets.		
23028044		4/3/2023	1190 Pine Grove Ave	Pine Grove Ave	A large depression on the asphalt has formed from the edge of the paving to the sanitary sewer manhole.		Insspected on 7/13/2023. No repairs have been completed.
23020683		4/6/2023	3320 Woodrow Way	Woodrow Way	Cuts to the road and shoulder were made for repairs to the sanitary sewer lateral to this property. The trench was repaired with GAB and no road plates have been installed		The paving has been completed. The remaining repairs are for the concrete C&G.
23029792		4/6/2023	2533 Skyland Trl	Skyland Trl	A sinkhole has developed at the edge of the road with the granite curb above the water service line to this property. A safety cone was placed over the depression on the road.		

215 Total Locations Requiring DWM Repairs (DWM Work Orders)	169 Known DWM Work Orders Completed, 8/20-Present	25 Locations with Roa
-------------------------------------------------------------	---------------------------------------------------	-----------------------

215 Total Locations Requiring DWM Repairs (DWM Work Orders)		169 Known DWM Work Orders Completed, 8/20-Present			25 Locations with Road Plates Covering Needed Repair		
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
23029788		4/6/2023	3273 Stratfield Dr	Stratfield Dr	A long depression has from 3280 to 3273 above the sanitary sewer main and between two manholes and Lift Station #50		Inspected on 7/13/2023. No repairs have been completed.
		5/4/2023	3653 Brookleigh Ln	Brookleigh Ln	A large sinkhole is forming on the beauty strip at the entrance of Brookleigh Ln on Ashton Woods. The sinkhole is above the mater main.		
		5/16/2023	4006 E Brookhaven Dr	IF Brookhaven Dr	A four-foot by two feet wide sinkhole has formed in front of this property DW. A safety Barrel has been installed over the sinkhole.		Inspected on 7/13/2023. No repairs have been completed.
		5/17/2023	3241 Woodrow Way	Woodrow Way	Repairs to the water main were made and 3 sections of the sidewalk were removed. 3 additional sections of the sidewalk were damaged during the repairs. While GAB was added, no safety cones were installed.		The sidewalk has been repaired. The forms have not been removed. Inspected on 7/13/2023
23043296		5/31/2023	3174 Cates Ave		A depression has been forming for the last 3 years above the sanitary sewer main in front of this property. It has become dangerous for pedestrians and cyclists while using the street.		
23404374		6/6/2023	1271 Star Dr	Star Dr	A 6 feet long by 4 feet wide sinkhole has formed on the street above this property's sanitary sewer service line. The sinkhole is approximately 4 feet deep and the City has installed two safety barrels Over 3 months ago, a sinkhole formed over the sanitary sewer lateral from this property to the main. The first response from DWM indicated that no problems were found with the SS main. However, this is an SS lateral issue. Please, send a crew that can CCTV the SS lateral and provide us with the results of the inspection. Ultimately, the City of Brookhaven will fill the sinkhole with concrete if no response is received from DWM		

September 2023

215 Total Locations Requiring DWM Repairs (DWM Work Orders)		169 Known DWM Work Orders Completed, 8/20-Present			25 Locations with Road Plates Covering Needed Repair		
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
23048398		6/20/2023	2577 Ashford Rd	Ashford Rd	Repairs to the water service lateral to this property have been completed once before on the shoulder of the street. Now a large depression has formed in the street in line with the previous repairs. The depression is 4 feet wide by 6 feet long and 4 inches deep. Please, treat this as an emergency and send a crew asap.		
		6/20/2023	3262 Woodrow Way	Woodrow Way	A depression has been forming at the intersection of Breton Circle and Woodrow Way. The City of Brookhaven has twice in the past, added pavement level with the street, and has continued to drop. Depression is occurring near the sanitary sewer main.		inspected on 8/21/23
		6/21/2023	3968 Ashford Dunwoody Rd	Ashford Dunwoody Rd	Scheduled work for the installation of a new water service line which resulted in an open cut in the middle of the street, and the removal of a section of sidewalk. A road plate has been installed.	х	The street is to be repaired by A&S Paving. No schedule has yet been provided.
23051082		7/3/2023	2835 Duncan Dr	Duncan Dr	A sinkhole has formed over the SS service line to this property. The sinkhole was filled with GAB by the City of Brookhaven PW. And is pending action by DWM.		
23059186		8/8/2023	1217 Kendrick Rd	Kendrick Rd	During the recent storm events, a large depression/sinkhole has formed above the sanitary sewer main. It is 6 feet long by 3 feet wide and continues to grow. A few feet from the depression, a crack in the street from curb to curb has formed. It continues to the shoulder at 1220 Kendrick Rd where another sinkhole is forming.		
23061312		8/16/2023	1701 Dresden Dr	Dresden Dr	There is a sinkhole developing behind the granite curb and inline with the water service lateral to this property. The sinkhole continues underneath the roadway towards the center of the street. Please, send a crew to investigate whether this is related to the water or sanitary sewer laterals.		
		8/22/2023	3206 Osborne Rd	Osborne Rd	A depression above the water main has been observed. There are 3 valve covers that have sunk with the street and need to be raised once the street is repaired		
23063796		8/25/2023	1000 Byrnwyck Rd	Byrnwyck Rd	A water leak has developed behind and underneath the concrete C&G.		
		8/30/2023	3856 Parkcrest Dr	Parkcrest Dr	Recently, DWM completed repairs on a water service line at this address. The trench was filled with GAB instead of placing a road plate as it is required by Dekalb County and the City of Brookhaven Trench standards. This section of Parkcrest is on a steep slope and recent rain events have created a 4-foot deep by 6-foot long sinkhole at the edge of the pavement. Please, treat this as an emergency and send a crew to install a road plate over the trench today.		

15 Total Locations Requiring DWM	Repairs (DWM Work Orders)	169 Known DWM Work Orders Completed, 8/20-Present	

215 Total Locations Requiring DWM Repairs (DWM Work Order		(DWM Work Orders)	169 Known DWM Work	Orders Completed, 8/20-Present	25 Locations with Road Plates Covering Needed Repair		
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
		9/8/2023	1889 Curtis Dr	Curtis Dr	A water main occurred near a gate valve. Repairs were completed by DWM however the trench and the shoulder have not been repaired. The site was not secured with caution tape.		
		9/18/2023	1770 Duke Rd	Duke Rd	Repairs to the water main underneath the driveway to this property were completed last week. GAB was installed on the driveway. The street was severely compromised during the water break and repairs. At least half of the street must be milled and paved.		
23071560		9/18/2023	1508 Cortez Ln	Cortez Ln	A sinkhole has formed above the sanitary sewer main		
21087723	8/9/2023	9/8/2022	2896 Caldwell Rd	Caldwell Rd	10-FT of the sidewalk was removed for repairs to the water main. GAB and no safety cones, barrels, or caution tape were installed.		The sidewalk has been repaired. Forms have not been removed and landscape restoration has yet to be completed. The surface of the new SW is substandard.
22088462	7/19/2023	9/15/2022	2673 N. Thompson Rd.	N. Thompson Rd.	There is a sinkhole forming in the middle of the street above the sanitary line.		DWM CCTV their line and found no issues. Insist it is for the COB to repair. Repaired by the PW Dept.
	7/19/2023	11/15/2022	1302 W. Nancy Creek Rd	W. Nancy Creek Rd	DWM was called out for an emergency water leak at the service meter for this house. They repaired the line that was exposed to part of the driveway and washed away part of the front yard.		It has been repaired.
23005011 23005284	4/11/2023	1/6/2023 2/10/2023	3528 Telfair Way	Telfair Way	The concrete curb and gutter and one lane of the road have been removed for repairs to the water main. GAB was added to the trench.		Repaired on 4/11/23
	7/20/2023	1/24/2023	1754 Tryon Rd	Tryon Rd	DWM did repairs to the water or sanitary in the residents yard, they removed the granite curb. They will need to reset the granite curb.		It has been repaired.

15 Total Locations Requiring DWM Repairs (DWM Work Orders)	169 Known DWM Work Orders Completed, 8/20-Present
------------------------------------------------------------	---------------------------------------------------

215 Total Locations Requiring DWM Repairs (DWM Work Orders)		169 Known DWM Work Orders Completed, 8/20-Present			25 Locations with Road Plates Covering Needed Repair		
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
23000298	4/11/2023	2/15/2023	1441 Lanier Manor	Lanier Manor	A cut in the road and the beauty strip was made for repairs to the water service line to this property on October 12th of 2022.		It has been repaired.
23017344	4/25/2023	2/22/2023	1546 Windsor Pkwy	Windsor Pkwy	A depression has formed above the sanitary sewer service line to this property. It is 2 feet wide and 3 inches deep and it extends towards the sidewalk.		Repaired by the PW Dept.
	1/9/2023	10/4/2022	2430 Coosawattee Dr	Coosawattee Dr	A sinkhole has developed in the beauty strip. The nearest utility is the sanitary sewer and we have reported it to DWM for further inspection		The sinkhole was repaired by OPTECH with WO 8673
21048724 22023281	1/17/2023	5/24/2021 3/14/2022	1855 Tobey Rd NE	Tobey Rd NE	A sinkhole formed 6-ft deep, 6-ft in length, and, 4-feet wide underneath the road in line with the sanitary sewer line from this property to the middle of the road. The sinkhole was repaired with WO 21048724. It was noted on 3/11/2022 that it had reopened and no concrete cap was installed on the trench.		Inspected 1/17/23 completed,
22072849	1/23/2023	11/14/2022	2968 Cravenridge Dr.	Cravenridge Dr	The crosswalk to the Ashford Park Elementary School was removed and damaged by DWM during maintenance to the water main. The sidewalk at the end of the crosswalk was partially repaired with asphalt including the trip hazards.		The sidewalk is being repaired by OPTECH with WO 8702.
	1/24/2023	8/24/2022	1697 Wawona Terrace	Wawona Terrace	Emergency repairs for a water main break. The repairs to the road and landscaping are scheduled to be completed by 8/26/22		Inspected 1/24/23 completed.
	1/24/2023	10/31/20222	1855, 1861 Dresden Dr	1861 Dresden Dr	Residents reported DWM completed sanitary sewer work but the shoulder is sinking.		Inspected 1/24/23 no change.
22036495	1/30/2023	4/28/2022	3847 Granger Dr	Granger Dr	The concrete collar of manhole # 18-325-s130 is broken and is causing the road to break around it.		The repairs to the catch bsain is being done by Corbett.
2063959	2/2/2023	8/19/2020	4180 4352 4368 Berkford Circle	4352 4368 Berkford Circle	A depression in the road 3-inches deep formed last year and no repairs have been made. First reported on 8/29/2020.		Repairs have been completed

215 Total Locations Requiring DWM Repairs (DWM Work Orders)				169 Known DWM Work	Orders Completed, 8/20-Present	25 Locations with Road Plates Covering Needed Repair		
	Observed							

215 Total Loc	215 Total Locations Requiring DWM Repairs (DWM Work Orders)		169 Known DWM Work Orders Completed, 8/20-Present			25 Locations with Road Plates Covering Needed Repair		
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES	
21069929	2/3/2023	8/3/2021	1514 Ragley Hall Rd NE	Ragley Hall Rd NE	A depression formed underneath the sidewalk. The sidewalk collapsed 3-inches above the sanitary and water service lines to this property.		Repairs have been completed	
21091053	2/3/2023	9/28/2021	2332 Drew Valley Rd	Drew Valley Rd	There is a large depression over the sanitary sewer service line in the middle of the road.		Repairs have been completed	
21094283	2/3/2023	10/12/2021	3882 Ashford Dunwoody Rd	Ashford Dunwoody Rd	DWM made repairs to a water main break and damaged the sidewalk at both ends and behind of it. The water break caused the sidewalk to sink before the catch basin creating a trip hazard. DWM has to demo and repair the sidewalk. The repairs were made the first week of October.			
22001232	2/3/2023	1/11/2022	2638 Drew Valley Rd	Drew Valley Rd	Repairs to a water valve and water main were made and it damaged the ADA ramp. The water valve was left above the surface of the road.		Repairs have been completed	
22037156	2/3/2023	5/2/2022	1310 Ragley Hall Rd	Ragley Hall Rd	Two depressions in the road have been observed. One is across a water leak and above the SS and the other is above the SS main near manhole # 18-302-s066.		Repairs have been completed	
	2/3/2023	10/4/2022	2420 Drew Valley Rd	Drew Valley Rd	The shoulder of the road, granite curbs, and pavement were disturbed for repairs to the water main and the service line to this property. Mulch was installed but no other repairs made.		Repairs have been completed	
22083979	2/3/2023	10/13/2022	1414 Ragley Hall Dr	Ragley Hall Dr	3 sections of the sidewalk were removed for repairs to the water main. GAB was added, and seed and straw to the shoulder and beauty strip.		Repairs have been completed	
22016627 COB	2/10/2023	2/22/2022	2925 Skyland Dr	Skyland Dr	A sinkhole has developed at the edge of the road with the granite curb in line with the water service line to this property. DWM has stated the sinkhole not related to the water main underneath of it.		Inspected 9/15/2022, PW called Atl. Gas& light to check for a possible gas leak, nothing was found. Will notify the owner of what was found. The homeowner will repaired it.	
22071998	2/10/2023	8/19/2022	4279 Ashwoody Trl NE	Ashwoody Trl NE	There is a large amount of water flow from the water meter at this property flowing into the road and the stormwater is equivalent to 5 gallons per minute.		The repairs have been completed.	

215 Total Locations Requiring DWM Repairs (DWM Work Orders)	169 Known DWM Work Orders Completed, 8/20-Present
-------------------------------------------------------------	---------------------------------------------------

215 Total Locations Requiring DWM Repairs (DWM Work Orders)			(DWM Work Orders)	169 Known DWM Work Orders Completed, 8/20-Present			25 Locations with Road Plates Covering Needed Repair		
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES		
22084419	2/10/2023	9/23/2022	4082 Nancy Creek Way	Nancy Creek Way	Emergency repairs to the water service line to this property were made on 9/22/22. Mud and sediments were left on the road and in the stormwater conveyance system.		The repairs to the shoulder have been completed and the road is clean.		
	2/10/2023	10/4/2022	1583 Fearn Circle	Fearn Circle	Repairs to a water service lateral to this property were completed but not all the sod was installed.		The landscape has been completed		
21062135	3/8/2023	7/12/2021 1/18/2022	2622 Briarcliff Rd NE	Briarcliff Rd NE	Pothole has opened up once more due to contact water spewing from it. First reported on 7/12/21. The City of Brookhaven Street crew repaired only the pothole due to the delay by DWM responding to our SR. A second SR has been submitted on 10/6/21. DWM has excavated the pothole and installed a road plate.	х	The cuts in the road have been repaired.		
22059814	3/21/2023	7/12/2022	1448 1457 1466 Grant Dr.	1457 1466 Grant Dr.	A large depression has formed in the road above the sanitary sewer main and where the service line to this property is located.		The concrete cap plus the repairs to the road have been completed by A&S Paving, a subcontractor for DWM.		
	3/21/2023	9/22/2022	2297 Nesbitt Dr	Nesbitt Dr	A trench to the middle of the road has been made and an excess amount of GAB added to it. The GAB has created a hump in the street. Additionally, the shoulder of the road was disturbed and has not been repaired.		The concrete cap plus the repairs to the road have been completed by A&S Paving, a subcontractor for DWM.		
22097532	3/21/2023	11/21/2022	2455 Ellijay Dr.	Ellijay Dr.	DMW purform a point repair that had been reported by the homeowner.		The concrete cap plus the repairs to the road have been completed by A&S Paving, a subcontractor for DWM.		
	3/21/2023	1/12/2023	2396 Coosawattee Dr.	Coosawattee Dr.	Water has been found entering the stormwater pipe underneath the road at a constant flow rate. Unable to determine the location of the leak, we have contacted DWM to investigate the water service lateral to 2395 Coosawattee Dr.		The road has been repaired by A&S Paving. A contractor for DWM.		
23020563	3/23/2023	3/6/2023	3193 LeConte Ave.	LeConte Ave.	A new concrete curb and gutter were built by the PW Dept. at the intersection of Inman Dr and LeConte Ave. A DWM truck responding to an emergency water leak at 3180 LeConte Ave run over the curb breaking it in three places. The DWM supervisor, Theodore Travis was on the scene and was provided with pictures of the incident.		Repaired by Optech		

L5 Total Locations Requiring DWM Repairs (DWI	M Work Orders) 169 Kno	wn DWM Work Orders Complet	ed, 8/20-Present

215 Total Locations Requiring DWM Repairs (DWM Work Orders)		169 Known DWM Work Orders Completed, 8/20-Present			25 Locations with Road Plates Covering Needed Repair		
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
22060218 22082176	3/28/2023	7/8/2022 9/1/2022 2/13/2023	3308 Finistere Ct	Finistere Ct	A 3x3 and 8 inches deep sinkhole has formed over the water service line to this property. The City isntalled cones and a barrel with caution and a request was made to DWM to install a road plate.		The road has been repaired.
22073233 22100092	4/10/2023	8/16/2022 11/22/2022	2572 Apple Valley Rd	Apple Valley Rd	A 4-FT deep sinkhole has formed at the edge of the concrete sidewalk near the sanitary sewer service line and between the cleanup and the manhole in the middle of the street.	х	The road has been repaired.
22088465 22091310	4/10/2023	9/15/2022 2/10/2023	3192 Caldwell Rd.	Caldwell Rd.	DWM did an emergency repair on the sanitary lateral, they backfilled with GAB. There is no plate over the hole.		The road has been completely repaired.
21117119	4/10/2023	9/20/2022	1970 E Roxboro Rd.	E Roxboro Rd.	Repairs were made to a DWM pipe, they placed a steel plate over the hole.	х	The road has been completely repaired on 4/10/2023
23007895	4/10/2023	12/21/2022	1300 Hermance Dr	Hermance Dr	Repairs to the water main were conducted by DWM. The northbound lane was removed and GAB was added to the trench. Rain events have continuously washed away		The road has been completely repaired on 4/10/2023
	4/10/2023	4/6/2023	1661 Tryon Rd	Tryon Rd	Road repairs are underway by A&S Paving		The road has been completely repaired on 4/10/2023
	5/16/2023	9/22/2022	1518 Grant Dr	Grant Dr	A depression has developed on a patch previously repaired by the City.		
	6/5/2023	3/8/2023	3901 Ashford Dunwoody Rd	Ashford Dunwoody Rd	Approximately 30 feet of the sidewalk have been damaged or removed for repairs to the water main. GAB has been added to the removed sections of the sidewalk.	х	The sidewalk has bee repaired.
23010654	6/8/2023	2/8/2023	2012 E Roxboro Rd	E Roxboro Rd	A metal plate was installed for repairs to the water main. The plate shifted and motorists are avoiding it by driving on the opposite lane	х	Street repairs completed on 6/8/23

5 Total Locations Requiring DWM Repairs (DWM Work Orders) 169 Known DWM Work Orders Completed, 8/20-Presen

215 Total Locations Requiring DWM Repairs (DWM Work Orders)			(DWM Work Orders)	169 Known DWM Work Orders Completed, 8/20-Present			25 Locations with Road Plates Covering Needed Repair		
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES		
	6/8/2023	6/6/2023	3929 Ashford Dunwoody Rd	Ashford Dunwoody Rd	Road plates have been placed over recent emergency repairs by DWM	x	Street repairs completed on 6/8/23		
	6/14/2023	9/15/2022	1314 Beech Haven Dr	Beech Haven Dr	A water service line has hit and is leaking at the enttrance to the park. DWM came out and dug up two locations but did not repair the leak. They covered the holes with GAB. Water is running into the street.		Repaired by A&S Paving		
23048393	6/20/2023	6/20/2023	3251 Breton Circle	Breton Circle	A depression has been forming at the intersection of Breton Circle and Woodrow Way. The City of Brookhaven has twice in the past, added pavement level with the street, and has continued to drop. Depression is		An inspection by DWM Water found no leakage however it was found a probable sanitary sewer failure. Will report it under 3262 Woodrow Way		
22052846	6/27/2023	6/17/2022	2794 Ashford Rd	Ashford Rd	A sinkhole has developed next to repairs made by DWM to another sinkhole at 2791 Ashford Rd.		Repairs have been completed		
22075222 22103460	6/27/2023	8/23/2022 1/30/2023	2791 Ashford Rd	Ashford Rd	Under the previous repairs for DWM WO 21079815, the sewer laterals for 2791 and 2794 were repaired but the COB or Dekalb Trench Standards were not followed. A benched concrete cap was not installed and the road was not milled and paved from BOC to BOC. The road has begun to sink between these two repairs		Inspected on 6/5/23. Pending repair schedule from DWM		
23000654	6/27/2023	1/17/2023	2929 Surrey Ln	Surrey Ln	DWM performed a repair to the sanitary line, tyhey bckfilled the hole with 57 stone and GAB. There is no road plate and the stones and GAB is washing out down the street.		Inspected 1/17/23		
23010194	6/27/2023	2/15/2023	1861 Tobey Rd	Tobey Rd	A cut in the road was made for repairs to the sanitary sewer lateral to this property. GAB was added and some has washed away.				
	7/10/2023	1/12/2023	2271 Fairway Circle	Fairway Circle	The driveway and the shoulder of the road have been removed for repairs to the water main.		The repairs have been completed.		
23035233	7/10/2023	5/17/2023	3268 Breton Circle	Breton Circle	A cut to the middle of the road was made for repairs to the sanitary sewer service line to this property. GAB was added to the trench.		The paving has been completed.		
22018437	7/13/2023	2/28/2022	2367 Ewing Dr	Ewing Dr	A sinkhole has formed underneath the concrete cap installed by DWM.		The old line is to be abandoned and replaced with a new line later this year by DWM.		
22018437	7/13/2023	2/28/2022	2373 Ewing Dr	Ewing Dr	A sinkhole has formed underneath the concrete cap installed by DWM.		The old line is to be abandoned and replaced with a new line later this year by DWM.		

215 Total Locations Requiring DWM Repairs (DWM Work Orders)			(DWM Work Orders)	169 Known DWM Work Orders Completed, 8/20-Present			25 Locations with Road Plates Covering Needed Repair		
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES		
	7/13/2023	3/31/2022	1552 Brawley Circle	Brawley Circle	A 3-inch depression has formed in the road above the sanitary sewer main.		The depression will be repaired with the street pavement repairs scheduled for 2024 by the COB		
22036023	7/13/2023	4/26/2022	4166 Candler Lake W	Candler Lake W	3 depressions have formed above the SS main which have caused the entire road to further break.		The depression will be repaired with the street pavement repairs scheduled for 2024 by the COB		
22036023	7/13/2023	4/26/2022	4128 Candler Lake W	Candler Lake W	A large depression has formed in the middle of the road above the SS mainline. The depression is in line with the SS service line to this property.		The depression will be repaired with the street pavement repairs scheduled for 2024 by the COB		
22036028	7/13/2023	4/26/2022	4046 Candler Lake W	Candler Lake W	A large depression has formed from the curb to the middle of the road. A locate811 has been requested as this depression may be water or sewer.		The depression will be repaired with the street pavement repairs scheduled for 2024 by the COB		
22082319	7/13/2023	9/14/2022	2933 Parkridge Dr	Parkridge Dr	A minor water leak around the water meter has caused the granite curbs to collapse. Due to the slope of the front yard, the water is traveling underneath the granite curbs. We have replaced some granite curbs and will wait for DWM to investigate the leak before completing our repairs.		The leak has stopped and the granite curbs have not collapsed. 7/13/2023		
22089511	7/13/2023	10/12/2022	2765 Osborne Rd	Osborne Rd	A water leak underneath the driveway to this property was reported to DWM.		The leak has been repaired.		
	7/13/2023	10/13/2022	3505 Hampton Hall Way	Hampton Hall Way	DWM repair the water main on the shoulder of the road. The shoulder has not been restored.		The shoulder has been restored.		
	7/13/2023	10/24/2020	1247 Oostanula Dr	Oostanula Dr	The driveway and part of the road were removed for repairs to the water main and lateral to this home. GAB was added to the driveway and mud was not removed from the road.		The driveway and pavement have been repaired.		
	7/13/2023	1/12/2023	3298 Osborne Rd	Osborne Rd	Failure of a previous repair under WO 22086487 has caused the front yard to collapsed		The shoulder of the street has been repaired.		
23010658	7/13/2023	2/8/2023	2065 Brook Forest Dr	Brook Forest Dr	A Sinkhole has formed in the road in line with the water service to this property.		The sinkhole has been repaired.		

September 2023

215 Total Loc	215 Total Locations Requiring DWM Repairs (DWM Work Orders)		(DWM Work Orders)	169 Known DWM Work Orders Completed, 8/20-Present			25 Locations with Road Plates Covering Needed Repair		
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES		
23028165	7/13/2023	4/3/2023	1426 Kendrick Rd	Kendrick Rd	A crack in the road traversing the sanitary sewer manhole has appeared.		DWM inspected and found no issues.		
21063205	7/13/2023	7/15/2021	1896 E Roxboro Rd NE	IF Roxboro Rd NF	Work on fire hydrant. Tree on the sidewalk and sinkhole at edge of it. DWM cones installed. There is a small sinkhole next to the fire hydrant.		The shoulder of the road has been repaired.		
22046688	7/20/2023	5/27/2022 4/10/2023	3707 Lambert Ln		The original sinkhole was repaired by the COB PW. Another sinkhole has formed in the road 4 times larger than the original	х	To be repaired by A&S Paving. No scheduled has been provided. 7/13/2023		