

**DWM Incomplete/Completed Work Areas
in
Brookhaven Rights-of-Way
May 2024**

242 Total DWM Work Orders Created

211 Known DWM Work Orders Completed, 8/20-Present

DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
21085424 24033585 24039571		9/14/2021 4/3/2023 4/11/2024	4560, 4588 E Brookhaven Dr	4588 E Brookhaven Dr	A large depression has formed in the middle of the road near the sanitary sewer line. A sinkhole has formed around the manhole on the cul-de-sac.		Two other depressions over the sanitary sewer main and laterals have formed. Inspected on 4/11/2024
21091564 22001249 23012287		10/1/2021 01/13/2022	2484 Oostanaula Dr. NE	Oostanaula Dr. NE	The road has been poorly repaired with no concrete cap. The entire asphalt patch is sinking.		Inspected on 3/15/2024
22011262 24030116		2/1/2022 3/19/2024	1451, 1456 Sylvan Circle	1456 Sylvan Circle	A depression has formed in the middle of the road along with the sanitary sewer mainline. The depression is approximately 6-ft long by 3-ft wide and 3-inches deep.		Inspected 4/11/2024 the repair has not been completed.
22015961		2/18/2022	1537 Aragon Way	Aragon Way	In the middle of the road above the Sanitary Sewer line and at the edge of a trench the road is sinking.		Inspected on 11/2/2023
		9/1/2022	1285 Old Johnson Ferry Rd	Old Johnson Ferry Rd	A valve was installed in the ADA ramp area and a ramp was poured back around the water valve. This does not comply with ADA codes, the valve has to be relocated. 11/14/2022		Inspected on 3/12/2024
22097416		11/14/2022	1242 Goodwin Rd	Goodwin Rd	A depression in the road has developed. The depression has developed above the sanitary sewer lateral.	X	Inspected on 3/15/2024
23020321		3/2/2023	2573 Skyland Trail	Skyland Trail	3 large sinkholes and a small one have formed above and in front of the water main alongside the frontage of this property.		Inspected on 3/14/2024
23028044 24028753		4/3/2023 3/15/2024	1190 Pine Grove Ave	Pine Grove Ave	A large depression on the asphalt has formed from the edge of the paving to the sanitary sewer manhole. This has continue to dropped.		Insspected on 3/15/2024. No repairs have been completed.
23029788		4/6/2023	3273 Stratfield Dr	Stratfield Dr	A long depression has from 3280 to 3273 above the sanitary sewer main and between two manholes and Lift Station #50		Inspected on 3/12/2024. No repairs have been completed.

**DWM Incomplete/Completed Work Areas
in
Brookhaven Rights-of-Way
May 2024**

242 Total DWM Work Orders Created

211 Known DWM Work Orders Completed, 8/20-Present

DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
		9/18/2023	1770 Duke Rd	Duke Rd	Repairs to the water main underneath the driveway to this property were completed last week. GAB was installed on the driveway. The street was severely compromised during the water break and repairs. At least half of the street must be milled and paved.		Inspected on 2/27/24
23073739 23073740		11/2/2023	1158 W Nancy Creek Dr	W Nancy Creek Dr	A water leak underneath the driveway of this property was repaired. A new driveway and two sections of the sidewalk were installed. However, the new driveway slope is 4 and 5% which does not meet ADA requirements.		Inspected on 1/3/24
23084017		11/7/2023	3188 Inman Dr	Inman Dr	The road is caving in above the sanitary sewer main.		Inspected on 1/3/24
23027989		4/3/2023	3292 Buford HWY	Buford HWY	On the N Cliff Valley Way side of the AMR building. The shoulder has yet to be repaired by DWM.		Inspected on 11/7/2023.
21105504 23062530		11/2/2023	1082 Mendell Circle	Mendell Circle	A sinkhole has developed next to a previous DWM street repair.		
23094219		12/18/2023	1093 W Nancy Creek Dr	W Nancy Creek Dr	A sinkhole has formed near the center of the street and the SS main. PW investigated and found a sinkhole underneath the street. A temporary patch was installed and DWM notified.	X	Inspected on 3/15/2024
23092868		11/12/2023	1879 Tobey Rd	Tobey Rd	A sinkhole has developed above the SS main.		
23092868		12/15/2023	1899 Tobey Rd	Tobey Rd	A sinkhole has formed in the middle of the street above the SS main.	X	Inspected on 1/4/2024

**DWM Incomplete/Completed Work Areas
in
Brookhaven Rights-of-Way
May 2024**

242 Total DWM Work Orders Created

211 Known DWM Work Orders Completed, 8/20-Present

DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
24003372		1/17/2024	2743 Redding Rd	Redding Rd	A large depression has developed above the SS in the middle of the street.		Inspected on 1/17/2024
2059434 2059640 23082146		8/7/2020 10/30/2023	1462 Brawley Circle	Brawley Circle	A depression above the sanitary sewer main developed early last year. This was previously reported, however, no work has ever been observed to repair the pavement. Please send a crew to investigate and make the necessary repairs. Remember that poor compaction at the time the sanitary sewer was installed causes the pavement to sink and DWM is responsible for the repairs.		Last reported on 1/19/2024
22018437		2/28/2024	2373 Ewing Dr.	Ewing Dr.	The length of the concrete cap installed by DWM over 12 years ago over the water main is collapsing due to poor compaction and not being installed to the Dekalb Watershed trench details standards. The entire concrete cap has to be removed. The trench soils have to be tested and properly compacted. The concrete cap repair following the City of Brookhaven Trench details as it is being done for the new water main on Drew Valley Rd.		Inspected on 3/15/2024
24003372		1/13/2024	2743 Redding Rd	Redding Rd	A large depression has formed above the SS main in the middle of the street.		Inspected on 4/11/2024
24019882		2/28/2024	1754 Duke Rd	Duke Rd	The ADA ramp has been removed for repairs to the water main. GAB was installed but not safety cones or caution tape. The GAB has a washout at the edge with the pavement creating dangerous conditions for pedestrians.		Inspected on 2/27/2024. The shoulder of the road has been repaired.
24033841		3/27/2024	1483 Grant Dr	Grant Dr	A depression across the street has formed which could be water or sanitary sewer related.		
24033868		3/28/2024	1161 Victoria St	Victoria St	A previously repaired SS service line by DWM is failing. The concrete gutter and part of the driveway have sunk.		

**DWM Incomplete/Completed Work Areas
in
Brookhaven Rights-of-Way
May 2024**

242 Total DWM Work Orders Created

211 Known DWM Work Orders Completed, 8/20-Present

DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	DESCRIPTION	Road Plate Used	UPDATES
24029694		3/26/2024	2834 Duncan Dr	Duncan Dr	A deep sinkhole has developed at the water meter and towards the middle of the street.		
24003949		4/10/2024	2806 Redding Rd	Redding Rd	At the request of the property owner, DWM cut open the street for repairs to the SS service line.		The street is to be repaired by AS Paving on 5/8/2024
24041492		4/16/2024	1879 Tobey Rd	Tobey Rd	A sinkhole has formed above the sanitary sewer main.		
24039812		4/16/2024	1514 Donaldson Park Dr	Donaldson Park Dr	The sidewalk has been removed for repairs to the water service lines.		
24046623		4/29/2024	2206 Drew Valley Rd	Drew Valley Rd	SS sewer lateral repairs were made back in 2022 by DWM and point repairs on 2023 by RGI however, the street continues to sink towards this property. Please send a crew to investigate and make the necessary repairs. This section of the street is to be repaved by the Renee Group under contract by DWM Sewer this year		
24003366		1/17/2024	2403 Coosawattee Dr	Coosawattee Dr	A previous DWM SS repair is sinking.		